

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Wednesday, 15 January 2025 5:30 PM
To: Darren
Cc: Shiau Chan (LKKAuto)
Subject: Re: YP286L TP China After paints and Items

Hi Darren,

As per my message to Samantha,

We will be advising our principal a cost of repair L/S \$3,750.00 /- with 05 days of repair before GST, subject to their approval.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Darren <darren@sngahtee.com>
Sent: Wednesday, 15 January 2025 9:44 am
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: YP286L TP China After paints and Items

Hi Rasul,

The items that are found damages are:

Frt bumper bracket \$120

Frt door hinge bottom \$80

Frt door checker \$100

The supplementary items are

Frt corner panel clip \$4.5x2

Frt door glass regulator \$355

Frt side mirror arm cap \$6.5

Frt door hinge top \$80

Please view the photos in the email.

Thank you

Best Regards

Darren Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
HP: 91181186
TEL: 62686183 (4LINES)
FAX: 62681429

Find us at <http://www.sngahtee.com>

