



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2503025

INV Date 16/05/2025

Reference CD/LPC24100446/Ema3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 7701D
Insured Veh. XE 1392B
Claim No. 24/24/24/VC05/030088
Policy No. Z24VC05022147
Accident Date 15/10/2024
Inspection Date 19/12/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24100446/Ema3q2(N)	
			Date: 16/05/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 1392B	Veh. Inspected	XE 7701D
	Policy No.	Z24VC05022147	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030088	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	19/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO FMX460	c.c	12777
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	YV2XTY0A0NA305471	Colour	WHITE
	Odometer	76638 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm
	L/H Front Tyre	295/80 R22.5	BRIDGESTONE	5 mm
	R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	5 mm
	L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/10/2024	Inspection Date	19/12/2024
	Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 7701D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TOP REINFORCEMENT (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CHASSIS MEMBER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CHASSIS MEMBER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR CHASSIS MIDDLE BRACKET (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-	-
			-	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR CARPLATE (SN)	BENT	35.00	35.00
1	REAR STICKER 50KM/H (SN)	NECESSARY	60.00	30.00
1	REAR REFLECTOR STICKER (SN)	NECESSARY	200.00	100.00
1	TAIL LAMP RH (SN)	BROKEN	850.00	300.00
1	TAIL LAMP LH (SN)	NOT NECESSARY	850.00	-
1	TAIL LAMP INNER BRACKET RH (SN)	NOT NECESSARY	485.00	-
1	TAIL LAMP INNER BRACKET LH (SN)	NOT NECESSARY	485.00	-
1	REAR LOWER REINFORCEMENT TOP BRACKET RH (SN)	BENT	800.00	250.00
1	REAR LOWER REINFORCEMENT TOP BRACKET LH (SN)	BENT	800.00	250.00
1	REAR LOWER REINFORCEMENT (SN)	DENTED	2,700.00	800.00
			7,265.00	1,765.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS .INCLUSIVE OF THE REPAIR OF REAR TOP REINFORCEMENT ,REAR CHASSIS MEMBER RH,REAR CHASSIS MEMBER LH AND REAR CHASSIS MIDDLE BRACKET.		1,000.00	600.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,000.00	600.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS .	NOT NECESSARY	90.00	-

Report Ref No. CD/LPC24100446/Ema3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPAIR CHASSIS MEMBER RH .		400.00	400.00
	REPAIR CHASSIS MEMBER LH .		400.00	100.00
			2,890.00	1,700.00
GRAND TOTAL			10,155.00	3,465.00
RECOMMENDED COST OF REPAIRS				3,465.00

Report Ref No. CD/LPC24100446/Ema3q2(N)

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 7701D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 7701D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 7701D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

