

Not Noted
 Primary Bt pain

AAD2410-059

8/200h

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD283J

Vehicle No.:
 Chassis No.:
 Co UEN.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

25 OCT 2024

SHD283J
 JTDKB3FU303096994
 200303878K
 TOYOTA
 PRIUS GEN 4
 21/10/24
 SLM 8931A/TB
 4/9/2023

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 COVER, DECK TRIM, REAR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

LIST

\$	Bu	612.68	✓
\$	Sn	27.93	X
\$	Out/In	472.19	✓
\$	Sn	149.21	X
\$	Sn	149.21	X
\$	Dis	167.48	✓
\$	Sn	167.48	X
\$	Sn	419.90	X
\$	Sn	49.25	X
\$	Sn	428.19	} X
\$	Sn	329.49	
\$	Sn	88.41	
\$	Sn	220.50	
\$	Sn	304.92	
\$	Sn	290.43	
\$	Sn	1,099.46	
\$	Sn	176.09	
\$	Sn	159.39	
\$	Sn	1,156.89	
\$	nn	68.88	
\$	nn	68.88	
\$	nn	90.30	
TOTAL \$		6,697.16	
25% \$		1,674.29	
\$		5,022.87	

SPECIAL NETT

- 1SET PARKING AID
 1 REAR BUMPER CLIP

\$ Sn 700.00 X
 \$ Sn 65.00 605m

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2410-**SHD283J**

- 1 REAR RH BUMPER RETAINER CLIP
- 1 FENDER LINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR

\$	~	65.00	X
\$	~	65.00	X
\$	~	60.00	X
\$	~	180.00	X

TOTAL \$ 1,135.00**TOTAL PARTS \$ 6,157.87****LABOUR**

To rust-proofing of the affected areas.

\$ ~ 600.00 X

Putty and spray painting of the affected portion.

\$ 1,200.00 220/

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 200/

To transfer of tailgate fittings and conduct water seepage test.

\$ ~ 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ ~ 380.00 X

To transfer of tailgate fittings and conduct water seepage test.

\$ ~ 170.00 X

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ ~ 170.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 50/

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

TOTAL \$ 5,080.00**OVERALL TOTAL \$ 11,237.87**

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days