

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	23/10/2024
Vehicle Reg. No.:	SHA2042R	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ, 1.6 (A)	Vehicle Reg. Date:	27/02/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU406579	Chassis No:	KMHC851CVLU189287
Odometer:	540375 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,980.08
Miscellaneous Items	12.00
Labour	780.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,772.08
+ GST 9.00% (\$\$)	249.49
Nett Amount (\$\$)	3,021.57

This claim is handled by: LOKE WEI YIENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Oct 2024)
 Parts: 143 HYUNDAI IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHA2042R/24/10/2024 15:07
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER x R / BR	20.00	0.00	*459.40 FL /
2	1		*REAR BUMPER CLIPS x nn / Nec	20.00	0.00	*22.00 FL /
3	1		*REAR BUMPER CENTRE MOULDING ASSY OR	20.00	0.00	*451.25 FL /
4	1		*REAR BUMPER REINFORCEMENT ? x nn	20.00	0.00	*394.80 FL
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH ? x nn	20.00	0.00	*138.10 FL
6	1		*ANTENNA SMARTKEY x nn	20.00	0.00	*40.50 FL
7	1		*REAR BUMPER FOG LAMP ? x nn	20.00	0.00	*201.50 FL
8	1		*REAR BUMPER TOWING COVER X nn	20.00	0.00	*98.80 FL
9	1		*REAR NUMBER PLATE WITH TRIM COVER OR	0.00	0.00	*55.00 F / nett
10	1		*REAR BUMPER REVERSE SENSOR ? x nn	0.00	0.00	*180.00 F
11	1		*RENEW ADVERTISEMENT STICKER OR	0.00	0.00	*300.00 F / nett

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 2,341.35
 - List Item Discount on L Items (S\$) 361.27
 Total Parts (S\$) 1,980.08

ComfortDelGro Engineering Pte Ltd/SHA2042R/24/10/2024 15:07. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

932.65
 -20%
 746.12 + 355 (nett) = 1101.12

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00 /
Sub Total (S\$)			12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	380 400.00
2	SPRAY PAINTING CHARGE	New	280 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	70 80.00
Gross Labour Cost (S\$)			780.00 692

ComfortDelGro Engineering Pte Ltd/SHA2042R/24/10/2024 15:07. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
25/10/24, 3:07 PM
in IL
L/S
by ALG
2 djs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: