

ASS. REC. BY:

REF:

C12 /

CS/CT124100452/Knb3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 2932P

Yr Regn:

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Seat 1629

c.c

999

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

107219

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSS 8888JZ1R137747

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

21/10/24

D.O.I.

1/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No 2nd parts available

3/12 @ 2122-80 Cahul (Red. \$ 4070.90, 65%)

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

2

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fuel

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd**
3, Anson Road,
#16-00, Springleaf Tower,
Singapore 079909

Attn : Motor Claims Department
Tel : 6389 6111
Fax : 6222 1033

Estimate bill : TT 41 / 24 / TP / WT

Registration No : SLV2932P

Make / model : Seat Ibiza

Mileage : Date : 23 / 10 / 2024

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SNE8642C AND SLV2932P ALONG CLEMENTI ROAD ON 21 OCTOBER 2024 AT ABOUT 1710HRS.

1pc	Rear bumper	1131		\$	1,635.00	✓
2pcs	Rear bumper parking sensor (Centre)		(Each \$308.00)	\$	616.00	X
1pc	Rear bumper license plate garnish			\$	200.00	✓
1pc	Rear bumper reflector (LH)			\$	67.00	✓
1pc	Rear bumper lip			\$	424.00	✓
1pc	Rear silencer box			\$	1,352.00	X
1pc	Rear exhaust tail pipe adaptor			\$	549.00	X
	Sub A total :			\$	4,843.00	
	Less 10% discount :			\$	484.30	
	A total :			\$	4,358.70	

Special net items :

1pc	Rear license smart plate (Chrome lettering)		\$	180.00	✓
1pc	Rear license smart plate casing		\$	25.00	✓
	B total :		\$	205.00	

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parking sensor (Centre), rear bumper license plate garnish, rear bumper reflector (LH), rear bumper lip, rear silencer box, rear exhaust tail pipe adaptor.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear bumper, rear bumper parking sensors (Centre).

Grand final amount :

\$ 6,193.70

Tropical Tech Automobile Services



(Authorised Signature)
William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: