Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL: 6481 7773 / 6481 1403 FAX: 6484 4978

E-mail: tsac303@singnet.com.sg

China Taiping Insurance (Singapore) Pte. Ltd M/s:

Estimate bill: TT 41 / 24 / TP / WT

3. Anson Road,

#16-00, Springleaf Tower,

Registration No:

Singapore 079909

Resorry Afte Pain Make / model:

SLV2932P

Attn:

Motor Claims Department

Tel: 6389 6111 6222 1033 Fax:

Seat Ibiza

Mileage:

23 / 10 / 2024

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SNE8642C AND SLV2932P ALONG CLEMENTI ROAD ON 21 OCTOBER 2024 AT ABOUT 1710HRS.

Rear bumper 1131				2	1,033.00
Rear bumper parking sensor (Centre)			(Each \$308.00)		0.0.00
Rear bumper license plate garnish				Ψ	200.00
	¥ -				M 67.00
				\$	n 424.00
				\$ 12 54	
				\$ rn	549.00
				\$	4,843.00
				\$	484.30
				\$	4,358.70
Ti total .					451.
	Treat builtper	Rear bumper parking sensor (Centre) Rear bumper license plate garnish Rear bumper reflector (LH) Rear bumper lip Rear silencer box Rear exhaust tail pipe adaptor Sub A total: Less 10% discount:	Rear bumper parking sensor (Centre) Rear bumper license plate garnish Rear bumper reflector (LH) Rear bumper lip Rear silencer box Rear exhaust tail pipe adaptor Sub A total: Less 10% discount:	Rear bumper parking sensor (Centre) Rear bumper license plate garnish Rear bumper reflector (LH) Rear bumper lip Rear silencer box Rear exhaust tail pipe adaptor Sub A total: Less 10% discount:	Rear bumper parking sensor (Centre) Rear bumper license plate garnish Rear bumper reflector (LH) Rear bumper lip Rear silencer box Rear exhaust tail pipe adaptor Sub A total: Less 10% discount:

	Special net items:
1pc	Rear license smart plate (Chrome lettering)
1pc	Rear license smart plate casing
	B total:

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parking sensor (Centre), rear bumper license plate garnish, rear bumper reflector (LH), rear bumper lip, rear silencer box, rear exhaust tail pipe adaptor.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

NN 80.00 X

800.00

8

To check and refit rear tail lamp wiring harness.

Na 150.00 X

Under coating on rear damaged portion.

2201 600.00

Putty / primer application, spray painting rear bumper, rear bumper parking sensors (Centre).

6,193.70

Grand final amount:

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

(Authorised Signature)

William Tan