



Not Authorized  
 Name  
 28/10/24  
 P/P 9  
 2 days  
 The photo above.

**ASSESSMENT FOR REPAIR : FBW882B**

**HONDA CB200X**

**COE EXPIRY : 26.11.2033**

**Lump Sum / Part by Part**

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	HANDLE BAR <i>SVC</i>	110.00	X		
1	LH - HAND GUARD <i>3 road</i>	68.67	✓		
1	LH - FRONT VENT COWL <i>cut</i>	127.53	✓		
1	LH - FRONT VENT COWL EMBLEM <i>scr</i>	68.67	✓		
1	LH - TANK COWL <i>cut</i>	235.44	✓		
1	SIDE STAND <i>R</i>	29.43	X		
		639.74			

Special Nett Items

STEERING CONE & BEARING <i>11</i>	130.00	X		
FRONT FORK ALIGNMENT <i>11</i>	230.00	X		
WHEEL ALIGNMENT <i>11</i>	130.00	X		
FRAME ALIGNMENT <i>11</i>	210.00	X		

700.00

Total Parts

1,339.74

Labour Charges

1	Workmanship to renew damage parts & areas	400.00		
	\$100 per days X 4 days	400.00		

180

Total Parts & Labours Concluded

1,739.74

*F&K Auto Consultants*  
 I, the Repairer of the following:  
 - The repair work for repair of the  
 - In doing damaged parts,  
 - I hereby declare that all the  
 - I hereby declare that I am on a "Warranty"  
 - All repair, modification(s) is/are  
 - All necessary part(s) must be  
 - is subject to final approval from  
 Acknowledged by Repairer

SANFU MOTOR PTE LTD  
 Company Reg No.: 200612487G  
 1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883  
 Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010  
 Email: sanfumotor0243@gmail.com