

# EVI Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-19, Singapore 575722

Tel: 6456 0226 // Email: emautosolution@singnet.com.sg

Not Notified  
11 Sep @ 4950h  
Recovery After Paint  
4 days

Vehicle number: SLK1228D

Vehicle Made & Model: MERCEDES-BENZ GLB 180

| Qty        | List Items                               | Amount \$                  |
|------------|------------------------------------------|----------------------------|
| 1          | Tailgate                                 | R 4,581.22 X               |
| 1          | Tailgate glass                           | Sn 1,322.51 X              |
| 1          | Tailgate M/B star                        | Me 86.95 ✓                 |
| 1          | Tailgate emblem "GLB 180"                | Me 141.20 ✓                |
| 2          | Tailgate lamps - L/R @ 581.43            | MS Cut O/S Sn 1,162.86 X X |
| 1          | Tailgate inner lock                      | R 755.13 X                 |
| 1          | Tailgate inner lock cover                | Sn 192.96 X                |
| 1          | Tailgate w/strip                         | Sn 322.71 X                |
| 2          | Tailgate dampers - L/R @ 811.45          | Sn 1,622.90 X              |
| 2          | Tailgate stoppers - L/R @ 42.20          | Sn 84.40 X                 |
| 1          | Taillamp - LH                            | Sn 894.35 X                |
| 1          | Rear bumper - Top 1245.20                | Bu 1,655.93 ✓              |
| 1          | Rear bumper chrome plate - Top 320-10    | Me 611.42 ✓                |
| 1          | Rear bumper CTR pad 721                  | Pol/CM 811.33 ✓            |
| 1          | Rear bumper bottom chrome trim           | CNT 1,471.43 ✓             |
| 1          | Rear bumper bottom cover - CTR           | Sn 681.62 X                |
| 1          | Rear bumper reflector - LH               | CM 112.10 ✓                |
| 2          | Rear bumper PDC sensors - LH @ 281.33    | Sn 562.66 X                |
| 1          | Rear bumper reinforcement 680            | R 1,055.90 ✓               |
| 2          | Rear bumper side brackets - Top @ 115.20 | Sn 230.40 X                |
| 2          | Rear bumper lower brackets @ 110.20      | Sn 220.40 X                |
| 2          | Rear bumper side retainers - L/R @ 95.50 | Sn 191.00 X                |
| 1          | Rear end panel                           | R 1,015.60 X               |
| 1          | Rear end panel trim                      | Sn 180.93 X                |
| 1          | Rear exhaust chrome trim - LH 185.40     | RU 485.91 ✓                |
| 1          | Rear exhaust insulator                   | Sn 280.90 X                |
| 1          | Rear exhaust silencer                    | R 1,895.60 X               |
| 2          | Rear fender protectors - L/R @ 399.62    | Sn 799.24 X                |
| 1          | Rear foot activated sensor               | Sn 391.33 X                |
| Sub-total  |                                          | 23,820.89                  |
| Less 10%   |                                          | 2,382.09                   |
| Total List |                                          | 21,438.80                  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle number: SLK1228D

Vehicle Made & Model: MERCEDES-BENZ GLB 180

**Special Nett Items**

1 set Tailgate glass sealant  
1 set Rear bumper clip

|                           |               |   |
|---------------------------|---------------|---|
| <i>nn</i>                 | 120.00        | X |
| <i>nn</i>                 | 60.00         | ✓ |
| <b>Total Special Nett</b> | <b>180.00</b> |   |

**Labour charges**

To check rear electrical wiring  
To remove, refix tailgate glass  
Transfer & reinstall tailgate components to new tailgate  
To remove, refix rear interior trims to assist repair  
To remove, refix rear exhaust systems  
To respray undercoating  
To diagnose, erase fault memory after repair  
To respray painting and etc  
Panel beating, cut, weld remove & replacing above parts

|                     |                 |            |
|---------------------|-----------------|------------|
|                     | 50.00           | <i>200</i> |
| <i>nn</i>           | 180.00          | <i>180</i> |
| <i>nn</i>           | 150.00          | X          |
|                     | 120.00          | <i>500</i> |
| <i>nn</i>           | 120.00          | X          |
| <i>nn</i>           | 120.00          | X          |
| <i>nn</i>           | 350.00          | X          |
|                     | 1,200.00        | <i>600</i> |
|                     | 1,200.00        | <i>500</i> |
| <b>Total Labour</b> | <b>3,490.00</b> |            |

**ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 25,108.80**