

EMI SOLUTION PTE LTD

160 Sin Ming Drive, (Sin Ming Autocity), #03-19, Singapore 575722

Tel: 6456 0226 // Email: emautosolution@singnet.com.sg

Not Notified
L1 Rep & 4950h

Recovery After Paint
4 days

Vehicle number: SLK1228D Vehicle Made & Model: MERCEDES-BENZ GLB 180

Qty	List Items	Amount \$
1	Tailgate	R 4,581.22 X
1	Tailgate glass	Sm 1,322.51 X
1	Tailgate M/B star	Ma 86.95 ✓
1	Tailgate emblem "GLB 180"	Ma 141.20 ✓
1	Tailgate lamps - L/R @ 581.43	MS Car o/s Sm 1,162.86 X
2	Tailgate inner lock	R 755.13 X
1	Tailgate inner lock cover	Sm 192.96 X
1	Tailgate w/strip	Sm 322.71 X
2	Tailgate dampers - L/R @ 811.45	Sm 1,622.90 X
2	Tailgate stoppers - L/R @ 42.20	Sm 84.40 X
1	Taillamp - LH	Sm 894.35 X
1	Rear bumper - Top 1245.20	Bu 1,655.93 ✓
1	Rear bumper chrome plate - Top 320.10	Ma 611.42 ✓
1	Rear bumper CTR pad 721	Polcom 811.33 ✓
1	Rear bumper bottom chrome trim	Cnt 1,471.43 ✓
1	Rear bumper bottom cover - CTR	Sm 681.62 X
1	Rear bumper reflector - LH	CM 112.10 ✓
2	Rear bumper PDC sensors - LH @ 281.33	Sm 562.66 X
1	Rear bumper reinforcement 680	R 1,055.90 ✓
2	Rear bumper side brackets - Top @ 115.20	Sm 230.40 X
2	Rear bumper lower brackets @ 110.20	Sm 220.40 X
2	Rear bumper side retainers - L/R @ 95.50	Sm 191.00 X
1	Rear end panel	R 1,015.60 X
1	Rear end panel trim	Sm 180.93 X
1	Rear exhaust chrome trim - LH 185.40	RU 485.91 ✓
1	Rear exhaust insulator	Sm 280.90 X
1	Rear exhaust silencer	R 1,895.60 X
2	Rear fender protectors - L/R @ 399.62	Sm 799.24 X
1	Rear foot activated sensor	Sm 391.33 X
Sub-total		23,820.89
Less 10%		2,382.09
Total List		21,438.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle number: SLK1228D

Vehicle Made & Model: MERCEDES-BENZ GLB 180

Special Nett Items

1 set Tailgate glass sealant
1 set Rear bumper clip

<i>nn</i>	120.00	X
<i>nn</i>	60.00	✓
Total Special Nett	<u>180.00</u>	

Labour charges

To check rear electrical wiring
To remove, refix tailgate glass
Transfer & reinstall tailgate components to new tailgate
To remove, refix rear interior trims to assist repair
To remove, refix rear exhaust systems
To respray undercoating
To diagnose, erase fault memory after repair
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

	50.00	<i>200</i>
<i>nn</i>	180.00	X
<i>nn</i>	150.00	X
	120.00	<i>500</i>
<i>nn</i>	120.00	X
<i>nn</i>	120.00	X
<i>nn</i>	350.00	X
	1,200.00	<i>600</i>
	1,200.00	<i>500</i>
Total Labour	<u>3,490.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 25,108.80