

Name & Address

Motor Claims Department

ECICS LIMITED

7 Temasek Boulevard

#10-01 Suntec Tower One

Singapore 038987.

Email/Fax No

Contact No

Vehicle No.

SLW1199R

Brand & Model:

BMW X3 sDrive20i

Chassis/VIN No:

WBATS720209C38862

WIP#:

29463

Date:

24-Oct-24

Franchise:

BMW

Contact Person (Eurokars):

HUI WEN

Contact No (Eurokars):

6331 0680

Type of Claim:

THIRD PARTY

YEAR MODEL:

15/09/2020

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	REAR BUMPER <i>De /</i>	51 12 7488222	1		-	\$ 1,598.75
2	LOWRE BUMPER PANEL <i>SEA /</i>	51 12 7488230	1		-	\$ 793.60
3	COVER, TOWING <i>SEA /</i>	51 12 7953954	1		-	\$ 52.30
4	GUIDE FOR BUMPER RH <i>?</i>	51 12 7400666	1		-	\$ 143.85
5	GUIDE FOR BUMPER LH <i>?</i>	51 12 7400665	1		-	\$ 143.85
6	SIDE GUIDE, BUMPER LH <i>?</i>	51 12 7400667	1		-	\$ 184.95
7	SIDE GUIDE, BUMPER RH <i>?</i>	51 12 7400668	1		-	\$ 184.95
8	REINFORCEMENT COVER <i>?</i>	51 12 7400674	1		-	\$ 123.85
9	LOWER BUMPER UNDERRIDE GUARD <i>SEA /</i>	51 12 7417846	1		-	\$ 357.90
10	REAR REINFORCEMENT <i>?</i>	51 12 7400008	1		-	\$ 832.45
11	GASKET <i>?</i>	51 12 7400673	2		-	\$ 15.50
12	TAILGATE <i>bt /</i>	41 00 7494942	1		-	\$ 2,241.15
13	SLIDER <i>me /</i>	51 62 7401793	4		-	\$ 33.80
14	CLIP WITH SE <i>me /</i>	07 14 2754954	2		-	\$ 2.80
15	BLIND RIVET <i>me /</i>	07 14 9174618	4		-	\$ 12.60
16	ADHESIVE PAD <i>me /</i>	51 18 7134021	3		-	\$ 5.40
17	EXPANDING NUT <i>me /</i>	07 14 7429950	2		-	\$ 6.10
18	BMW LOGO <i>me /</i>	51 14 7499154	1		-	\$ 76.55
19	LABEL X3 <i>me /</i>	51 14 8737319	1		-	\$ 68.90
20	LABEL SDRIVE20i <i>me /</i>	51 14 8737322	1		-	\$ 103.35
21	BUMP STOP <i>me /</i>	51 31 2996980	2		-	\$ 10.40
22	REPAIR FLAT <i>me /</i>	83 19 2289285	1		-	\$ 154.00
23	VELCRO FASTE <i>me /</i>	51 31 8269160	4		-	\$ 12.00
24						\$ -

Sub-Total (Parts Price) \$ - \$ 7,159.00

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER , TAILGATE AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1700	\$ 2,550.00

REPAIR ESTIMATE

2	TO RESPRAY REAR BUMPER AND TAILGATE.	1880	\$ 2,320.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
4	TO SUPPLY REAR LICENCE PLATE WITH CASING	nett	\$ 70.00
5	TO TRANSFER THE TAILGATE MECHANISM.	nett	\$ 425 800.00
6	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	nett	\$ 560.00
7	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	nett	\$ 180.00
8	TO TRANSFER THE REVERSE SENSORS.	nett	\$ 250 500.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150 250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 500.00
11	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time: 28/10/24	Repair Days: 5 days / P/P	Excess:
---------------------------------	------------------------------	---------

Surveyor Remarks:

Rear
Up 90010068
Rear by paint

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 8,080.00

	REVISED	PRICE
Parts Price	\$ -	\$ 7,159.00
Labour Price	\$ -	\$ 8,080.00
Total (Initial Estimate)	\$ -	\$ 15,239.00
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 15,239.00
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 15,239.00
GST 9%	\$ -	\$ 1,371.51
GRAND TOTAL	\$ -	\$ 16,610.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: