

S L MOTOR REPAIR

TO	: ERGO	DATE	25/10/2024
VEHICLE NO	: SMX1072E (2009)		
VEHICLE MODEL	: TOYOTA ALTIS		
CHASSIS NO	: MR053ZEE106140743		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Dehid</i>	1	\$ 585.90	\$ 585.90
2	REAR BUMPER SIDE HOLDER <i>Neu</i>	2	\$ 38.20	\$ 76.40
3	REAR BUMPER REINFORCEMENT ROD <i>Neu</i>	1	\$ 152.60	\$ 152.60
4	REAR BUMPER SPONGE <i>Amold</i>	1	\$ 129.20	\$ 129.20
5	REAR BUMPER IMPACT BRACKET <i>Dented</i>	2	\$ 85.60	\$ 171.20
6	REAR BUMPER REFLECTOR <i>Neu</i>	2	\$ 69.20	\$ 138.40
7	REAR END PANEL <i>Dented</i>	1	\$ 686.40	\$ 686.40
8	REAR END PANEL TOP GARNISH <i>Dehid</i>	1	\$ 192.70	\$ 192.70
9	TAILLAMP <i>cut</i>	2	\$ 366.90	\$ 733.80
10	TAILLAMP PANEL <i>Repair</i>	2	\$ 195.40	\$ 390.80
11	TAILLAMP LOWER BRACKET <i>Neu Nec</i>	2	\$ 55.10	\$ 110.20
12	BOOTLID <i>Dented</i>	1	\$ 839.40	\$ 839.40
13	BOOTLID LOCK <i>Dented</i>	1	\$ 121.50	\$ 121.50
14	BOOTLID WEATHERSTRIPE <i>cut</i>	1	\$ 195.50	\$ 195.50
15	BOOTLID HINGE <i>Neu</i>	2	\$ 72.50	\$ 145.00
16	BOOTLID REFLECTOR <i>LH cracked, RH cut</i>	2	\$ 280.30	\$ 560.60
17	BOOTLID INNER TRIM <i>Neu</i>	1	\$ 172.10	\$ 172.10
18	BOOTLID OUTER CHROME MOULDING <i>Amold</i>	1	\$ 274.80	\$ 274.80
19	TOYOTA LOGO <i>?</i>	1	\$ 52.60	\$ 52.60
20	1.6 EMBLEM <i>Neu</i>	1	\$ 46.90	\$ 46.90
21	ALTIS EMBLEM <i>Neu</i>	1	\$ 48.50	\$ 48.50
22	COROLLA EMBLEM <i>Neu</i>	1	\$ 55.50	\$ 55.50
23	REAR FENDER INNER TRIM <i>2 LH</i>	2	\$ 338.70	\$ 677.40
24	REAR FENDER INNER SHIELD <i>Neu</i>	2	\$ 48.50	\$ 97.00
25	SPARE TYRE PANEL <i>Repair</i>	1	\$ 845.90	\$ 845.90
26	SPARE TYRE LOCK SCREW <i>Neu</i>	1	\$ 42.60	\$ 42.60
27	SPARE TYRE PANEL TOP BOARD <i>Neu</i>	1	\$ 240.20	\$ 240.20

4694.50
3520.87

TOTAL PRICE: \$ 7,783.10
LESS 25% \$ 1,887.27
S IB TOTAL PRICE: \$ 5,895.83

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00
2	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 280.00	\$ 280.00
3	REAR END PANEL TOP GARNISH CLIPS <i>Neu</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>Neu</i>	1	\$ 60.00	\$ 60.00
5	TAILLAMP SPONGE GASKET <i>RH Neu</i>	2	\$ 20.00	\$ 40.00
6	BOOTLID INNER TRIM BOARD CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00
7	BOOTLID OUTER CHROME MOULDING CLIPS <i>Neu</i>	1 SET	\$ 10.00	\$ 10.00
8	BOOTLID REFLECTOR SPONGE GASKET <i>Neu</i>	2	\$ 20.00	\$ 40.00

380

TOTAL : \$ 510.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	750	
3	WIRING CHECK	\$ 50.00	30	
4	TO SPRAY TUFF COAT	\$ 150.00	60	
5	TO REMOVE UPHOLSTERY	\$ 150.00	60	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
8	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	60	

1 To remove rear camera.

100 TOTAL: \$ 3,600.00
50

1860

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,405.83
TOTAL LABOUR COST: \$ 3,600.00
TOTAL REPAIR COST: \$ 10,005.83

Total: 5760.87

1/2 4.61c.

06 Days.

4.61c.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: