

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 29 Oct 2024

**Preliminary Advice**

Insured Vehicle No	: SNL8278J	Accident Date	: 21/10/2024
TP Vehicle No	: SJJ203K	Assignment Date	: 28/10/2024
Make	: VOLKSWAGEN TIGUAN	Est. Duration of Repair	: 5
Date of Inspection	: 28/10/2024		
Inspection At	: GUAN MOTOR WORKS (HQ) 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,179.48
Revised Amount	:S\$	6,177.47
Check Items (Estimated)	:S\$	4,368.94
Total	:S\$	10,546.41
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( x ) Lump Sum repair
  
- ( x ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.