

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

60 WOODLANDS INDUSTRIAL PARK Date: 05/03/2025 E4SINGAPORE 757705	100461/Unp3e2(N)
E4SINGAPORE 757705	
ATTN: HUA YEN Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)	
Insured Veh. SHB 5168L Veh. Inspected SNN 6183B	
Policy No. Coverage (\$) 0.00	
Claim No. TAX/10/24/2074 Excess (\$) 0.00	
Assign From HUA YEN Assign Date 25/10/2024	
2. Vehicle Particulars & Condition	
Make & Model TOYOTA NOAH HYBRID (A) c.c 1797	
Engine No. HIDDEN Year of Reg. 2023	
Chassis No. ZWR900112167 Colour BLACK	
Odometer 105326 KM Steering IN ORDER	
Brakes IN ORDER Modification NIL	
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre         205/60 R16         BOTO         6 mm	
<b>L/H Front Tyre</b> 205/60 R16 BOTO 6 mm	
R/H Rear Tyre         205/60 R16         BOTO         6 mm	
L/H Rear Tyre 205/60 R16 BOTO 6 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.	
5. General Information	
Accident Date 23/10/2024 Inspect Date / Time 25/02/2025 (	11:37 AM )
Survey held at OOHRAY RENTAL PTE LTD	
8 KAKI BUKIT AVENUE 4, #06-31, PREMIER @ KAKI BUKIT, SINGAPOF	RE 415875
5a. Remarks	
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.	3 000-\$4 000
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$:	σ,000 φ+,000
	3,000 <del>4</del> 4,000

Report Ref No. CS3/SMR24100461/Unp3e2(N)

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

DECD Anto Computer OAE Universal America

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$