



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

STRIDES PREMIER AUTOMOTIVE SERVICES PL	INV No.	AC2501301
60 WOODLANDS INDUSTRIAL PARK E4	INV Date	05/03/2025
SINGAPORE 757705	Reference	CS3/SMR24100461/Unp3e2
ATTN: HUA YEN	Code	SMR

PROFESSIONAL SERVICE FEE

Vehicle No.	SNN 6183B
Insured Veh.	SHB 5168L
Claim No.	TAX/10/24/2074
Policy No.	
Accident Date	23/10/2024
Inspection Date	25/02/2025

Description	Total
Pre-Repair Survey	128.00
Subtotal	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
STRIDES PREMIER AUTOMOTIVE SERVICES PL 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 ATTN: HUA YEN			Ref: CS3/SMR24100461/Unp3e2(N) Date: 05/03/2025 Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 5168L	Veh. Inspected	SNN 6183B
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/24/2074	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	25/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH HYBRID (A)	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2023
	Chassis No.	ZWR900112167	Colour	BLACK
	Odometer	105326 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	BOTO	6 mm
	L/H Front Tyre	205/60 R16	BOTO	6 mm
	R/H Rear Tyre	205/60 R16	BOTO	6 mm
	L/H Rear Tyre	205/60 R16	BOTO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5. General Information				
	Accident Date	23/10/2024	Inspect Date / Time	25/02/2025 (11:37 AM)
	Survey held at	OOHRAY RENTAL PTE LTD 8 KAKI BUKIT AVENUE 4, #06-31, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/SMR24100461/Unp3e2(N)

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B




PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B




PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B




PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.


19-9607198-R

REINSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B



PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SNN 6183B

