



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24100462/Anp3m4
50 RAFFLES PLACE #03-03	Date:	09/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 509U	Veh. Inspected	XD 8243H
Policy No.	-	Coverage	0
Claim No.	CMTD2403398/SYH	Excess	\$0.00
Assign From	SHIANG YI	Assign Date	25/10/2024

2. Vehicle Details

Make & Model	ISUZU FXZ77M	C.C	9839
Engine No.	6UZ1476967	Year of Reg.	16/12/2013
Chassis No.	JALFXZ77MD7000012	Colour	GREEN
Odometer	896006 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80R22.5	CREAONE	8
L/H Front Tyre	295/80R22.5	CREAONE	8
R/H Rear Tyre	295/80R22.5	CREAONE	8
L/H Rear Tyre	295/80R22.5	CREAONE	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2024	Inspection Date	28/10/2024
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days