



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24100463/Rqp3e2
3 TEMASEK AVENUE	Date:	22/11/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLZ 6062C	Veh. Inspected	SNH 7045S
Policy No.	-	Coverage	0
Claim No.	CLMOMVP000001611	Excess	\$0.00
Assign From	ELIZABETH	Assign Date	25/10/2024

2. Vehicle Details

Make & Model	TOYOTA SIENTA HYBRID STANDARD	C.C	1497
Engine No.	1NZ9410610	Year of Reg.	21/11/2022
Chassis No.	JTDZZ9H390L001131	Colour	BLACK
Odometer	143367 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60 R15	DUNLOP	6
L/H Front Tyre	185/60 R15	DUNLOP	6
R/H Rear Tyre	185/60 R15	DUNLOP	6
L/H Rear Tyre	185/60 R15	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2024	Inspection Date	28/10/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days