

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: NO:60 JALAN LAM HUAT CARROS CENTRE #05-68 5737869

HP: 98888885

SUPPLEMENTARY

Date: 11/11/2024
Vehicle: SNP5580J
Make / Model: HYUNDAI KONA OS

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	FRONT SUPPORT PANEL broken	1	\$ 1,125.00	\$ 1,125.00
				\$ 1,125.00
			Less 20%	\$ 225.00
			Total	\$ 900.00
	S/Nett items:			
				\$ -
	Labour to: FRONT			
1	REMOVE AND REFIR FRONT SUPPORT PANEL	1	\$ 400.00	\$ 400.00
				\$ 400.00
			Parts Replacement Amount	\$ 900.00
			Total Amount for Labour	\$ 400.00
			Total Amount	\$ 1,300.00

/

/

300 /

1200