

SIN YU SIN WORKSHOP

1 KAKI BUKIT AVENUE 6
#01-82 AUTOBAY SINGAPORE 417883

TO	: AIG	DATE	26/6/2024
VEHICLE NO	: SMH5262G (2019)	<i>Xiao Tony</i>	
VEHICLE MODEL	: MAZDA 6		
CHASSIS NO	: JM6GL1072K0311619		

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	FRONT NUMBER PLATE GARNISH <i>new</i>		58.90	✓
2	FRONT BUMPER <i>torn</i>		1211.90	✓
3	FRONT BUMPER SIDE HOLDER @48.90 <i>new</i>		97.80	✓
4	FRONT BUMPER REINFORCEMENT <i>Dented</i>		585.90	✓
5	FRONT BUMPER REINFORCEMENT COVER <i>torn</i>		190.40	✓
6	FRONT BUMPER TOW COVER <i>new</i>		47.20	+
7	FRONT BUMPER SPONGE <i>cracked</i>		103.40	✓
8	FRONT BUMPER BRACKET @60.80 <i>LH could</i>		121.60	60.80
9	FRONT BUMPER SENSOR @205.40 <i>new</i>		821.60	X
10	FRONT BUMPER LOWER GRILLE <i>could</i>		138.50	-
11	FRONT BUMPER TOP GARNISH <i>Repair</i>		320.50	+
12	FRONT BUMPER UNDERCOVER <i>new</i>		235.90	+
13	FRONT GRILLE <i>cracked</i>		673.80	✓
14	FRONT GRILLE LOGO <i>new</i>		107.90	✓
15	FRONT GRILLE CHROME MOUDLING @176.30 <i>could</i>		352.60	✓
16	HEADLAMP @4579.10 <i>LH could</i>		9158.20	3369
17	FRONT BRACE PANEL <i>new</i>		75.20	X
18	RADIATOR PANEL SUPPORT FRAME <i>could</i>		746.50	✓
19	REAR BUMPER <i>Dented</i>		1099.40	✓
20	REAR BUMPER SIDE HOLDER @42.50 <i>new</i>		85.00	X
21	REAR BUMPER REFLECTOR @53.90 <i>new</i>		107.80	+
22	REAR BUMPER TOW COVER @46.60 <i>new</i>		93.20	X
23	REAR BUMPER REINFORCEMENT <i>Dented</i>		583.30	✓
24	REVERSE SENSOR @210.60 <i>2 pieces damaged</i>		842.40	411.20
25	REVERSE SENSOR HOLDER @25 <i>new</i>		100.00	✓
26	REAR END PANEL <i>Repair</i>		542.20	+
27	REAR END PANEL TOP GARNISH <i>Dented</i>		180.10	-
28	REAR END PANEL ANTENNA SENSOR <i>new</i>		179.80	X
29	TAILLAMP @1592.30 <i>LH could</i>		3184.60	1592.30
30	BOOTLID <i>Dented</i>		1245.50	✓
31	BOOTLID LOCK <i>and</i>		184.90	✓
32	BOOTLID WEATHERSTRIPE <i>new</i>		287.40	+
33	BOOTLID REFLECTOR @758.90 <i>new</i>		1517.80	X
34	MAZDA LOGO		58.90	✓
35	MAZDA 6 WORDING <i>new</i>		65.10	✓
36	SKYACTIV EMBLEM		60.40	✓
			25465.60	
Less 20%			5093.12	20%

12941.70
10353.36

			20372.48	
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE	150	30.00	X
2	FRONT NUMBER PLATE HOLDER		30.00	X
3	FRONT BUMPER CLIPS		30.00	✓
4	FRONT BUMPER UNDERCOVER CLIPS		30.00	X
5	FRONT GRILLE CLIPS		30.00	✓
6	RADIATOR COOLANT		50.00	✓
7	REAR BUMPER CLIPS		30.00	✓
8	REAR BUMPER STICKER WRAP		280.00	X
9	REAR END PANEL SEALANT		60.00	X
10	REAR END PANEL TOP GARNISH CLIPS		20.00	✓
Total Parts			390.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR ASSESSMENT (\$\$)
LABOUR			
1	PANEL BEATING	2000.00	900
2	SPRAY PAINTING	1600.00	800
3	WIRING	100.00	60
4	TO APPLY TUFF COAT	150.00	40
5	TO REMOVE FRONT BUMPER SENSOR	100.00	50
6	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	120.00	60
7	TO REMOVE RADIATOR & TO TOP UP COOLANT	120.00	60
8	TO TRANSFER BOOTLID FITTINGS	150.00	60
9	TO REMOVE REAR CAMERA	100.00	50
10	TO REMOVE UPHOLSTERY	150.00	30
11	TO REMOVE REVERSE SENSOR	100.00	50
Labour Total :		4690.00	
TOTAL (PARTS & LABOUR):		25452.48	

2160

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 12663.36

L/S: 10.1K ✓

07 Days.