



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Lim Chen Wen Edmund	Cust No/Name /Mr Lim Chen Wen Edmund
Blk676C Yishun Ring Road	Reg No/Reg Date SNF8296M / 24/06/2022
#07-1944	Date In/Mileage / 0
Singapore 763676	Chassis No MMBSTA13ANH002342
Contact No Mobile: 86927988	Engine No 3A92UKH4603
	Make/Model MIT/22MY ATTRAGE 1.2 CVT (G01)
	Colour/Trim X08 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00147	Cash	24/10/2024/ 19:18		1210/ Lim Teng Keat	51018

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z TEXT				
TP CLAIM INCOME				
DOA 09/10/2024				
SUR				
00 REPAIR DAYS				640 960.00
E PNT88000				
TO REPLACE REAR BUMPER				
REPAIR ACCIDENT AFFECTED AREA				550 825.00
E PNT98000				
PAINT WORK ON REAR BUMPER				120 180.00
E PNT88000				
TO REMOVE & REFIT REAR PARKING SENSOR				X 150.00
A 54900099				
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				280 380.00
A 10028901				
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				20 80.00
M SUNDRY				
SUNDRIES				
M FACE,RR BUMPER	1.00	667.00	00.00	Rx 667.00

Tanphi 97495749
 upr 5/6/25 @ 330p
 - 3 days
 Resing after repair
 tanphi c/hkhanboon.

Confirm & accepted by

9% GST on	Nett	3,242.00
		291.78
Total Payable		3,533.78

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.