

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07193

Vehicle Insured : SLJ489D

Accident Date : 24-Oct-2024

Date : 24-Oct-2024

Our Ref : 024211 (CHINA) / CHAN

PAGE : 1

CHAN JINGZHONG  
43 BRIGHT HILL DRIVE  
#19-14  
Singapore 573894

*Not Withheld*  
*Liability @ 33000*  
*Recovery After Pains*  
*6 days*

## ESTIMATED COST OF REPAIR FOR MAZDA 3 SLR6353E

1 pc	Rear bumper fascia			1,128.00	✓
1 pc	Rear bumper reinforcement			563.00	✓
2 pcs	Rear bumper side retainer	@ S\$ 38.00		CM 76.00	✓
2 pcs	Rear bumper side bracket	@ S\$ 49.00		CM 98.00	✓
2 pcs	Rear bumper towing cover	@ S\$ 26.90		MT 53.80	✓
2 pcs	Rr bumper side clip c/w screw	@ S\$ 5.50		MT 11.00	✓
1 pc	Rear bumper centre top clip			CM 5.90	✓
1 pc	Rear end panel			B 530.00	✓
1 pc	End panel top garnish			B 89.00	✓
1 pc	Rear floor panel sponge			CM 158.00	✓

2,712.70

Less 20% : 542.54

- 1 pc Rear bumper reverse sensor(set)
- 1 pc Rear bumper clip (set)

To remove rear seat, trim board and carpet

To apply undersealing

To putty and spray replaced parts

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total : S\$ 3,980.16

Singapore Dollars Three Thousand Nine Hundred and Eighty and Cents Sixteen Only

2,170.16 2000  
300.00 sn  
30.00 sn

120.00 600

60.00 ✓

1000.00 900

900.00 800

*31670.96*  
*50 230.00*  
*1870.00*  
*354.96*  
*744.99*  
*2970.97*

*LIS*  
*2950.00*