

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07193

Vehicle Insured : SLJ489D
Accident Date : 24-Oct-2024

Date : 24-Oct-2024

Our Ref : 024211 (CHINA) / CHAN

PAGE : 1

CHAN JINGZHONG
43 BRIGHT HILL DRIVE
#19-14
Singapore 573894

*Not with a car
L1 Reg & 3300p
Recovery After Pain
6 days*

ESTIMATED COST OF REPAIR FOR MAZDA 3 SLR6353E

1 pc Rear bumper fascia	Alum	1,128.00	✓
1 pc Rear bumper reinforcement	R	563.00	✓
2 pcs Rear bumper side retainer	CM	76.00	✓
2 pcs Rear bumper side bracket	CM	98.00	✓
2 pcs Rear bumper towing cover	MT	53.80	✓
2 pcs Rr bumper side clip c/w screw	MT	11.00	✓
1 pc Rear bumper centre top clip	CM	5.90	✓
1 pc Rear end panel	R	530.00	✓
1 pc End panel top garnish	R	89.00	✓
1 pc Rear floor panel sponge	CM	158.00	✓

2,712.70

Less 20% : 542.54

- 1 pc Rear bumper reverse sensor(set)
- 1 pc Rear bumper clip (set)

To remove rear seat, trim board and carpet

To apply undersealing

To putty and spray replaced parts

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total : S\$ 3,980.16

Singapore Dollars Three Thousand Nine Hundred and Eighty and Cents Sixteen Only

*2,170.16 2000
300.00 sn
30.00 sn*

120.00 600

60.00 ✓

1000.00 900

900.00 800

*L15
2970.00
P1670.96
SN 230.00
L 1870.00
320.96
744.99
2979.97*