

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100471/KPA3Q2
Date: 09/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MPC0001723_06
Claimant Vehicle No : SNQ1790R Insured Vehicle No : SJQ7301C
Date of Loss: 24/10/2024 Nature of Claim: TP Claim No: MPC2024D0012704

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNQ1790R
Make & Model: AUDI Q5, 2.0 TFSI Quattro (A) Engine No: CNC055835
Reg. Date: 31/07/2015 (Man. Year: 2014) Chassis No: WAUZZZ8R4EA123982
Colour: White Odometer: 98258 km
Engine Capacity: 1984 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,436.15	5,146.78	8,289.37	61.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	950.00	2,280.00	70.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,666.15	6,096.78	10,569.37	63.42
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	16,666.15	4,900.00	11,766.15	70.60
+ GST 9.00/9.00% (S\$)	1,499.95	441.00	1,058.95	70.60
Nett Amount (S\$)	18,166.10	5,341.00	12,825.10	70.60
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Medical Costs (S\$)		87.01		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		5,830.19		

INSPECTION

Date of Assignment: 29/10/2024
Date Inspected: 29/10/2024 Inspected At: Sin Ming Autocare BFG Pte Ltd (HQ)
176, Sin Ming Drive #02-05, Sin Ming Autocare Complex
Singapore 575721
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2024)
Parts:	M1-SUV	AUDI Q5 2.0 TFSI Quattro (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNQ1790R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Bent	4,927.00 F	*3,716.00 FL
2	1		*FRONT DOOR CHROME RH	Warped	388.50 F	*388.50 FL
3	1		*FRONT DOOR PROTECTOR RH	Necessary	685.50 F	*685.50 FL
4	1		*REAR DOOR RH	Repair	4,927.00 F	*- FL
5	1		*REAR DOOR CHROME RH	Warped	388.50 F	*388.50 FL
6	1		*REAR DOOR PROTECTOR RH	Serviceable	547.50 F	*- FL
7	1		*SIDE MIRROR COVER RH	Scratched	285.15 F	*285.15 FL
8	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	255.00 F	*255.00 FL
9	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	255.00 F	*- FL
10	1		*REAR DOOR OUTER MOULDING RH	Serviceable	388.50 F	*- FL
11	1		*FRONT DOOR OUTER MOULDING RH	Serviceable	388.50 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	13,436.15	5,718.65
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	571.87
Total Parts (\$\$)	13,436.15	5,146.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	New	1,300.00	400.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION.	New	1,100.00	500.00
3	TO APPLY RUST-PROOFING ON REPAIRED, REPLACED DOOR.	New	150.00	30.00
4	TO WHEEL ALIGNMENT.	New	120.00	0.00
5	TO CHECK WIRING FUNCTIONS.	New	80.00	20.00
6	TO CALIBRATION, DIAGNOSTIC, CHECK AND RESET.	New	480.00	0.00
Gross Labour Cost (\$\$)			3,230.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >