

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24100472/UMA3Q2**Date:** 17/01/2025**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0002040
Claimant Vehicle No : FBN5973L **Insured Vehicle No :** PC363Y
 Date of Loss: 28/07/2024 Nature of Claim: TP Claim No: MFL2024D0012974

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN5973L**
 Make & Model: YAMAHA CZD300A / XMAX300, 292cc Engine No: H336E0043296
 Reg. Date: 12/11/2018 (Man. Year: 2018) Chassis No: MH3SH0846KK005074
 Colour: Black Odometer: 77470 km
 Engine Capacity: 292 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70-15 Rear Tyre Size: 150/70-14
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,728.00	250.20	2,477.80	90.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	463.00	410.00	53.00	11.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,191.00	660.20	2,530.80	79.31
+ GST 9.00/9.00% (S\$)	287.19	59.42	227.77	79.31
Nett Amount (S\$)	3,478.19	719.62	2,758.57	79.31
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		806.87		
Global Sum Settlement (S\$)		800.00		

INSPECTION

Date of Assignment: 28/10/2024
 Date Inspected: 28/10/2024 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
 BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
 Singapore 533758
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 09 Jan 2025)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN5973L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BODY FRONT UNDER RH	Cut	47.00 F	*47.00 FL	
2	1		*COWLING FRONT RH	Cut	63.00 F	*63.00 FL	
3	1		*PROTECTOR EXHAUST	Cut	95.00 F	*95.00 FL	
4	1		*SHIELD HEAT MUFFLER SIDE	Cut	63.00 F	*63.00 FL	
5	1		*GASKET MUFFLER	Necessary	10.00 F	*10.00 FL	
6	1		*EXHAUST REAR ASSY	Repair	2,450.00 F	*- FL	
					Sub Total (\$\$)	2,728.00	278.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	27.80
					Total Parts (\$\$)	2,728.00	250.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT EXHAUST REAR ASSY	New	80.00	80.00
2	SPRAY PAINT RH PILLION BAR AND RH FRONT COWLING	New	213.00	180.00
3	LABOUR QUOTED FOR DISMANTALLING AND INSTALLATION OF PARTS	New	170.00	150.00
			Gross Labour Cost (\$\$)	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >