



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100474/Avh3m4
75 BRAS BASAH ROAD	Date:	27/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 9680S	Veh. Inspected	SNU 828C
Policy No.	-	Coverage	0
Claim No.	MT/1300347-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	28/10/2024

2. Vehicle Details

Make & Model	PEUGEOT 3008	C.C	1598
Engine No.	10FJCC2373760	Year of Reg.	28/12/2017
Chassis No.	VF3M45GZWS272424	Colour	GREEN
Odometer	81815 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R18	PIRELLI	6
L/H Front Tyre	225/55R18	PIRELLI	6
R/H Rear Tyre	225/55R18	PIRELLI	6
L/H Rear Tyre	225/55R18	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/10/2024	Inspection Date	28/10/2024 (14:07)
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #02-03A AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days