

JNB 8887

Rear tailgate	R1	& 972.00	✓
" " lock	R	& 321.00	X
" " w/screen midg	Mu	& 112.00	—
" " emblem	Mu	& 45.00	—
" " Mazda 2	Mu	& 29.00	✓
" " weather strip	in	& 218.00	X
Rear bumper	Bu	& 696.80	—
" " retainer x2 @57.60	in	& 115.20	X
" " reverse sensor	rephat	& 300.00	sn 205sn
" no plate lamp x2 @126.20	alsnd	& 252.40	Lt
Rear taillamp LH	in	& 394.70	X
" end panel	R	& 529.60	X
" " " garnish	in	& 127.40	X

208

To repair and replace affected parts	& 900.00	50d. ✓
To spray paint on affected parts	& 1000.00	55d. —
To remove and refix rear w/screen	& 180.00	12d. —
To replace rear reverse sensor	& 100.00	50d. —
To check wiring	& 40.00	20d. —
To remove and refix rear garnishes	& 100.00	50d. —
Tuff Coat	& 100.00	30d. —

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized 4 days
L/Sing & 2450p
Resurvey After Paint