

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO JNB 8887

REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR TAILGATE	BENT	\$972.00	\$972.00		
1	REAR TAILGATE LOCK	TO REPAIR SEE LABOUR	\$321.00	\$0.00		
1	REAR TAILGATE W/SCREEN MLDG	NECESSARY	\$112.00	\$112.00		
1	REAR TAILGATE EMBLEM	NECESSARY	\$45.00	\$45.00		
1	REAR TAILGATE MAZDA 2	NECESSARY	\$29.00	\$29.00		
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	\$218.00	\$0.00		
1	REAR BUMPER	BUCKLED	\$696.80	\$696.80		
2	REAR BUMPER RETAINER @\$57.60	SERVICEABLE	\$115.20	\$0.00		
2	REAR NO PLATE LAMP @\$126.20	N/S DENTED	\$252.40	\$126.20		
1	REAR TAILLAMP LH	SERVICEABLE	\$394.70	\$0.00		
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$529.60	\$0.00		
1	REAR END PANEL GARNISH	SERVICEABLE	\$127.40	\$0.00		
	LESS 0.00 / 20.00% DISCOUNT		\$0.00	(\$396.20)		
			\$3,813.10	\$1,584.80		
	Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR BUMPER REVERSE SENSOR (SN)	DENTED/SHORTED	\$300.00	\$200.00		
			\$300.00	\$200.00		
	Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
	TO REPAIR AND REPLACE AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE LOCK AND REAR END PANEL		\$900.00	\$500.00		
	TO SPRAY PAINT ON AFFECTED PARTS		\$1,000.00	\$550.00		
	TO REMOVE AND REFIX REAR W/SCREEN		\$180.00	\$120.00		
	TO REPLACE REAR REVERSE SENSOR		\$100.00	\$50.00		
	TO CHECK WIRING		\$40.00	\$20.00		
	TO REMOVE AND REFIX REAR GARNISHES		\$100.00	\$50.00		
	TUFF COAT		\$100.00	\$30.00		
			\$2,420.00	\$1,320.00		
GRAND TOTAL			\$6,533.10	\$3,104.80		
		<u> </u>	, 1,10 1100			



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)	\$2,450.00
Report Ref No: CS/AGI24060237/Kqh3e2	

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.