

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang
East Coast Centre
Singapore 438180
Fax: 63449773

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : w5 71560		Page No. : 1 of 4	
Date Estimated : 22/10/2024			
Prepared By : Muhammad Salleh Mahmood			

- ESTIMATE REPAIR FOR - Man Soon Tim Blk 475 Pasir Ris Drive 6 11-554 Singapore 510475	- ACCOUNT - 41000 Cash Sales - Svc Motorcycles PML
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FBT5129B	WB10L5109N6F31012	11/03/2022	R NINET	3665

DESCRIPTION	VALUE
Accident damage repair <i>650 x 1</i>	650.00
Total Labour 1:	650.00

PART NUMBER	DESCRIPTION	QTY	PRIC	VALUE
07119904950	O-RING (27X3.2) <i>/ npc</i>	1	4.98	4.98
11127698958	SCREW WITH BUSH <i>/ m</i>	2	27.90	55.80
11127923660	SEAL SET CYLINDER HEAD COVERS <i>/ npc</i>	1	96.44	96.44
11129898648	RH ROCKER PANEL BOX COVER (GRANITGR) <i>/ cut</i>	1	378.68	378.68
12139443071	Cover, ignition coil left <i>/ cut</i>	1	41.64	41.64
12139443072	Cover, ignition coil right <i>/ cut</i>	1	41.64	41.64
Total Parts :				619.18

Steno CLKK

4/11/24, 3:30pm

2 days

p/p

My Bel m

Labour 1	:	650.00
Parts	:	619.18
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	114.23
Grand Total	:	1,383.41

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **