



Final Report

Estimate No. : **w5 71560**
Date Estimated : **22/10/2024**
Prepared By : **Muhammad Salleh Mahmood**

Page No. : **1 of 4**

- ESTIMATE REPAIR FOR -

Man Soon Tim
Blk 475 Pasir Ris Drive 6
11-554

Singapore 510475

- ACCOUNT -

303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FBT5129B	WB10L5109N6F3101	11/03/2022	R NINET	7725

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Accident damage repair	650.00	0.00	650.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
O-RING (27X3.2)		1.00		4.98 #
SCREW WITH BUSH		2.00		55.80 #
SEAL SET CYLINDER HEAD COVERS		1.00		96.44 #
RH ROCKER PANEL BOX COVER (GRANITGR		1.00		378.68 #
LH IGNITION COIL COVER		1.00		41.64 #
RH IGNITION COIL COVER		1.00		41.64 #

SUPPLEMENTARY ITEMS

Total Labour :	650.00
Total Parts :	619.18
Total Labour & Parts :	1,269.18
Deduction for Excess :	
Total Repair Costs less Excess:	1,269.18
GST @9%:	114.23
Grand Total :	1,383.41

Performance Motors Limited.

BMW Motorrad
1 Ubi Road 4, Singapore 408607

Tel: 1800-2255-269
Co Reg No. 197401559W