


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 23.10.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNJ2079S**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 23.10.2024
TIME OF ACCIDENT : 08:30 HOURS

Veron

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Del'd</i>	1	\$ 2,402.40	\$ 2,402.40
2	FRONT BUMPER FOG LAMP LH <i>2</i>	1	\$ 516.10	\$ 516.10
3	FRONT BUMPER FOG LAMP HOUSING LH <i>1</i>	1	\$ 81.20	\$ 81.20
4	FRONT BUMPER SIDE CHROME LH <i>1</i>	1	\$ 231.20	\$ 231.20
5	FRONT BUMPER TOWING COVER LH <i>2</i>	1	\$ 28.60	\$ 28.60
6	FRONT BUMPER SIDE RETAINER <i>2</i>	2	\$ 103.40	\$ 206.80
7	FRONT BUMPER SPONGE <i>1</i>	1	\$ 99.30	\$ 99.30
8	FRONT BUMPER SENSOR HOLDER <i>2</i>	2	\$ 32.20	\$ 64.40
9	HEADLAMP (LED) LH <i>Can't</i>	1	\$ 11,325.30	\$ 11,325.30
10	FRONT SUPPORT PANEL <i>new</i>	1	\$ 1,561.20	\$ 1,561.20
11	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 248.50	\$ 248.50
12	WASHER TANK <i>new</i>	1	\$ 487.60	\$ 487.60
13	FRONT FENDER LH <i>Der'd</i>	1	\$ 1,312.50	\$ 1,312.50
14	FRONT FENDER COWLING LH <i>Del'd</i>	1	\$ 259.30	\$ 259.30
15	FRONT FENDER SUPPORT BRACKET LH <i>2</i>	1	\$ 85.20	\$ 85.20
16	FRONT STEERING RACK & PINION	1	\$ 1,955.30	\$ 1,955.30
17	FRONT KNUCKLE ARM LH <i>1</i>	1	\$ 734.80	\$ 734.80
18	FRONT LOWER ARM LH <i>1</i>	1	\$ 815.30	\$ 815.30
19	FRONT STABILIZER BAR LINKAGE LH	1	\$ 165.20	\$ 165.20
20	FRONT SHOCK ABSORBER LH	1	\$ 519.10	\$ 519.10
21	FRONT WHEEL HUP C/W BEARING LH	1	\$ 670.30	\$ 670.30

895

10500

985

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNJ2079S**
 MODEL : **TOYOTA ALPHARD**
 DATE OF ACCIDENT : 23.10.2024
 TIME OF ACCIDENT : 08:30 HOURS

22	SIDE MIRROR LH <i>Ry</i>	1	\$ 1,690.00	\$ 1,690.00
----	--------------------------	---	-------------	-------------

14094.30
10570.72

TOTAL PRICE \$ 25,459.60
 LESS 25% \$ 6,364.90
SUB TOTAL PRICE \$ 19,094.70

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
4	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	FRONT WHEEL TYRE LH <i>new</i>	1	\$ 680.00	\$ 680.00
7	FRONT WHEEL SPORT RIM (SET) <i>new</i>	1	\$ 2,800.00	\$ 2,800.00
8	BRAKE OIL <i>new</i>	1	\$ 40.00	\$ 40.00

60

TOTAL \$ 3,900.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>500</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>400</i>
3	TURFF COAT	\$ 250.00	<i>X</i>
4	WIRING CHECK	\$ 250.00	<i>30</i>
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>X</i>
6	REMOVE AND REFIX AND RESET FRONT SENSOR	\$ 80.00	<i>50</i>
7	REMOVE, REFIX AND RESET FRONT RADAR SENSOR	\$ 800.00	<i>X</i>

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNJ2079S**
MODEL : **TOYOTA ALPHARD**
DATE OF ACCIDENT : 23.10.2024
TIME OF ACCIDENT : 08:30 HOURS

8	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 850.00	x
9	FOUR WHEEL ALIGNMNET	\$ 120.00	x
10	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 380.00	x
11	RESET ABS LIGHT	\$ 200.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	x

TOTAL \$5,490.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 22,994.70
TOTAL LABOUR COST : \$ 5,490.00
TOTAL REPAIR COST : \$ 28,484.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
2/8 25/10/24,
04 Days

total: 11610.72
L/S: 9250 ✓

880