



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

KNA144815VJ 7208163

SMA3593B KIA CARENS 1.7

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy with lower lip <i>Delint.</i>	\$ 985.00
2	1	Front bumper side bracket-rear right <i>could</i>	\$ 85.00
3	1	Vent cover-rear right <i>Delint</i>	\$ 110.00
4	1	Rear reflector <i>could</i>	\$ 240.00
5	1	Tailgate logo and emblem full set <i>new</i>	\$ 200.00
6	1	Rear right fender light <i>Pyg</i>	\$ 880.00
7	1	Rear right tailgate light <i>could</i>	\$ 680.00 243.
8	1	Rear reinforcement <i>could</i>	\$ 780.00 428.
9	1	Tailgate side guide fits-out of shape <i>new</i>	\$ 180.00
10	1	Rear end side panel <i>Pyg</i>	\$ 950.00
11	1	Side panel bracket <i>new</i>	\$ 120.00
12	1	Rear fender <i>Pyg</i>	\$ 980.00
13	1	Tailgate rubber garnish <i>new</i>	\$ 250.00
14	2	Sensor-left <i>1 piece damaged</i>	\$ 500.00
15	1	Rear fender light left <i>could</i>	\$ 968.00 397
16	1	Rear reinforcement <i>Reperented</i>	\$ 785.00
17	1	Rear right side rim <i>new</i>	\$ 950.00
18	1	Rear right side wheel bearing <i>new</i>	\$ 650.00
19	1	key less <i>new</i>	\$ 280.00
20	1	Lower cover right <i>torn</i>	\$ 130.00
21	1	wheel arch mug guard <i>new</i>	\$ 280.00
Parts Sub-total			\$ 10,988.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMA3593B KIA CARENS 1.7

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>new</i>	\$ 100.00 30.
###	8	Rear tailgate inner board clips <i>new</i>	\$ 80.00
4	10	Rear fender light clips <i>new</i>	\$ 60.00
5	20	Rear right door clips <i>new</i>	\$ 100.00
6	1	Rear number plate and casing <i>new</i>	\$ 150.00
8	20	Wheel arch cover clips <i>new</i>	\$ 120.00
7		Special Nett Items Total	\$ 610.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SMA3593B

Modle: SMA3593B KIA CARENS 1.7

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 30
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00 50
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 1,600.00 800
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear side panel in & out, touch up fender	\$ 1,800.00 600
5	Carry out wheel alignment	\$ 120.00 +
6	Removing and installing rear fender compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00 60
7	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00 +
8	Checking central lock system for proper function	\$ 120.00 +
9	Carry out diagnosis check including cleaning accident fault code	\$ 150.00 +
10	Wheel balancing	\$ 80.00 +
11	Checking rear bumper sensor and harness for proper functioning	\$ 80.00 50
Total labour :		\$ 4,500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$4,081.20

x20%

= \$3264.96

l/s \$3250 and 5 days

Adm Cj
H/s 28/10/24
05 days