

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

Tel: 6468-2200 fax: 6278-5535

GST:200000606-K RCB NO: 200000606-K

ALLIED WORLD ASSURANCE COMPANY LTD
60 ANSON ROAD #08-00
SINGAPORE 079914

Estimate No. : WQ70002183

Date : 26-Oct-24

Policy No : SD24V04867 /VPZ /R07

Veh Reg No : **SLZ8750L**

ATTN: MOTOR CLAIM DEPARTMENT

Make / Model SSANGYONG STAVIC
2.0D AUTO 2WD 9 SEATER

Your Ref No : SLZ8750L

Claim Type : Third Party

Accident Date : 18/10/2024

TP Veh Reg No : XE4155A

Chassis No : KPTV081TSHP122598

Engine No : 67196022688010

Reg.Date : 16/11/2017

Estimate Repair Cost to Vehicle No :SLZ8750L

DESCRIPTION	QTY	LIST PRICE	AMOUNT
1 PNL ASSY-TAILGATE <i>Repair</i>	1	\$ 2,556.13	\$ 2,556.13 ✓
2 PNL ASSY-TAILGATE 'SSANGYONG' EMBLEM <i>re</i>	1	\$ 51.15	\$ 51.15 ✓
3 PNL ASSY-TAILGATE 'STAVIC' EMBLEM <i>XAN</i>	1	\$ 56.43	\$ 56.43 ✓
4 W/STRIP-TAIL GATE OPENING <i>XAN</i>	1	\$ 200.58	\$ 200.58 ✓
5 COMBI LAMP ASSY-RR QTR LH / RH <i>3x 7.50</i>	1	\$ 372.38	\$ 744.75 <i>372.38</i>
6 COMBI LAMP ASSY-T/GATE RR LH / RH <i>3x 7.50</i>	1	\$ 370.13	\$ 740.25 <i>370.13</i>
7 FASCIA-RR BUMPER <i>de</i>	1	\$ 1,936.43	\$ 1,936.43 ✓
8 LAMP ASSY-REFLEX REFLECTOR LH / RH <i>XAN</i>	2	\$ 53.83	\$ 107.65 ✓
9 BRKT ASSY-SIDE RR BUMPER LH / RH <i>7.50</i>	1	\$ 71.60	\$ 71.60 ✓
10 BRKT ASSY-SIDE R/BPR INR LH / RH <i>7.50</i>	1	\$ 56.73	\$ 56.73 ✓
11 ABSORBER-ENERGY RR BUMPER <i>7.50</i>	1	\$ 443.81	\$ 443.81 ✓
LIST TOTAL S\$: \$			9,466.97
10.00% DISCOUNT S\$: \$			946.70
			<u>\$ 8,520.27</u>

SPECIAL NETTS	QTY	UNIT PRICE	AMOUNT
1 TAILGATE GLASS SEALANT <i>XAN</i>	1	\$ 100.00	\$ 100.00 ✓
2 TAILGATE INNER TRIM BOARD CLIPS <i>XAN</i>	1	\$ 80.00	\$ 80.00 ✓
3 REAR BUMPER CLIPS <i>re</i>	1	\$ 80.00	\$ 80.00 <i>40 80.00</i>
5 REVERSE SENSOR <i>7.50</i>	1	\$ 350.00	\$ 350.00 <i>250 350.00</i>
			<u>\$ 610.00</u>

LABOUR CHARGE (LABOUR \$400 // SPRAY PAINT \$450)

\$5

1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE FRONT DAMAGED PARTS AND COMPONENTS	\$	2,000.00	800
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND AFFECTED AREA.	\$	1,350.00	700
3	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	\$	180.00	XMM
4	TO REMOVE AND REPLACE TAILGATE GLASS	\$	180.00	1200 XMM
5	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	\$	120.00	60
6	TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION	\$	180.00	1200 80

TOTAL : \$ 4,010.00
TOTAL PARTS : \$ 9,130.27
GRAND TOTAL : \$ 13,140.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2457.08

40.00

1840.00

4337.08

26%

3469.66

4 days

450/4 days

28/10/24

Res after repair

Repair

HP 900 10568