

ASS. REC. BY:

REF: 1051

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: \$105K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 11 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDK 99775 Yr Regn: 07, 18

Type: M/Gal / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 520i

c.c. 1998

Colour: M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 67092

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJA12020BJ19142

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: 245/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm

R/Bal. 8 mm

L/Bal. 2 mm

L/Bal. 8 mm

D.O.A. 20/10/24

D.O.I. 29/10/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / Midnight case, Barton Flat, GIA in Merimen

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1) _____
Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS, SI

F. 1000

Others

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

ump Sum / I.B.I: (\$

TOTAL

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Oct 2024)
 Parts: 143 BMW 520I LED NAV 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN GLASS	CM 0.00	0.00	*980.00 F	✓
2	1		*FRONT W/S GLASS MOULDING	MC 0.00	0.00	*85.00 F	✓
3	1		*STEERING AIR BAG	Bur 0.00	0.00	*2,350.00 F	✓
4	1		*STEERING AIR BAG COIL SPRING	MC 0.00	0.00	*1,260.00 F	✓
5	1		*PASSENGER AIR BAG	Bur 0.00	0.00	*1,750.00 F	✓
6	2		*FRONT AIR BAG SENSOR	MC 0.00	0.00	*560.00 F	✓
7	1		*AIR BAG CONTROL UNIT	MC 0.00	0.00	*1,460.00 F	✓
8	1		*FRONT DASHBOARD ASSY	MC 0.00	0.00	*4,900.00 F	✓
9	1		*ROOF LINING	return 0.00	0.00	*1,900.00 F	✓
10	2		*ROOF LINING AIR BAG	Bur 0.00	0.00	*1,880.00 F	✓
11	2		*FRONT SEAT SAFETY BELT	MC 0.00	0.00	*2,940.00 F	✓
12	2		*FRONT SEAT SAFETY BELT BUCKLE	0.00	0.00	*1,040.00 F	✓
13	3		*REAR SEAT SAFETY BELT	MC 0.00	0.00	*1,980.00 F	✓
14	3		*REAR SEAT BELT BUCKLE	0.00	0.00	*780.00 F	✓
15	1		*REAR BOOT BATTERY ACTUATOR	0.00	0.00	*290.00 F	✓
16	1		*REAR BOOT BATTERY ACTUATOR COVER	0.00	0.00	*350.00 F	✓
17	1		*BONNET	Bur 0.00	0.00	*2,870.00 F	✓
18	2		*BONNET HINGE	0.00	0.00	*330.00 F	✓
19	1		*BONNET LOGO	MC 0.00	0.00	*125.00 F	✓
20	1		*BONNET INSULATOR	MC 0.00	0.00	*410.00 F	X
21	2		*HEADLAMP	0.00	0.00	*7,600.00 F	✓
22	2		*HEADLAMP PANEL	0.00	0.00	*660.00 F	✓
23	1		*FRONT SUPPORT TOP PANEL	Bur 0.00	0.00	*290.00 F	✓
24	1		*FRONT SUPPORT TOP PANEL COVER	CM 0.00	0.00	*280.00 F	✓
25	1		*FRONT SUPPORT CENTRE PANEL	Bur 0.00	0.00	*155.00 F	✓
26	1		*SUPPORT PANEL REAR BRACKET	0.00	0.00	*180.00 F	✓
27	1		*FRONT V BAR	Bur 0.00	0.00	*112.00 F	✓
28	1		*FRONT REINFORCEMENT	MC 0.00	0.00	*780.00 F	✓
29	2		*FRONT REINFORCEMENT TOP BRACKET	MC 0.00	0.00	*18.00 F	✓
30	1		*FRONT BUMPER SPONGE	CM 0.00	0.00	*98.00 F	✓
31	1		*FRONT BUMPER INNER PARTS	0.00	0.00	*135.00 F	✓
32	1		*FRONT LOWER BEAM	0.00	0.00	*535.00 F	✓
33	2		*FRONT LOWER BEAM SIDE BRACKET	0.00	0.00	*140.00 F	✓
34	1		*FRONT LOWER BEAM FRONT COVER	0.00	0.00	*195.00 F	✓
35	1		*FRONT BUMPER FASCIA	Bur/CM 0.00	0.00	*1,700.00 F	✓
36	1		*FRONT BUMPER CENTRE BRACKET	0.00	0.00	*142.00 F	✓
37	2		*FRONT BUMPER SIDE INNER PART	0.00	0.00	*360.00 F	✓
38	2		*FRONT BUMPER SIDE RETAINER	0.00	0.00	*44.00 F	✓
39	1		*FRONT BUMPER LOWER GRILLE	CM 0.00	0.00	*175.00 F	✓
40	2		*FRONT BUMPER SIDE GRILLE	0.00	0.00	*378.00 F	✓
41	2		*FRONT BUMPER SIDE GRILLE CHROME	0.00	0.00	*270.00 F	✓
42	2		*FRONT BUMPER SIDE GRILLE INNER COVER	0.00	0.00	*170.00 F	✓
43	2		*FRONT GRILLE	CM 0.00	0.00	*420.00 F	✓
44	2		*FRONT BUMPER CENTRE PARKING SENSOR	MC 0.00	0.00	*440.00 F	✓
45	1		*AIR CON CONDENSER	Pur 0.00	0.00	*880.00 F	✓

Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
				0.00	0.00	*1,350.00 F	7
46	1		*RADIATOR ASSY	0.00	0.00	*130.00 F	7
47	1		*RADIATOR TOP GARNISH	0.00	0.00	*155.00 F	7
48	1		*AIR CON CONDENSER AIR VENT	0.00	0.00	*170.00 F	7
49	1		*AIR CON CONDENSER LOWER GUIDE	0.00	0.00	*1,580.00 F	7
50	1		*RADIATOR FAN MOTOR	0.00	0.00	*480.00 F	7
51	1		*RADIATOR FAN COWLNG	0.00	0.00	*60.00 FS	✓
52	1		*FRONT W/S GLASS SEALANT	0.00	0.00	*25.00 FS	✓
53	1		*ERP IU BRACKET	0.00	0.00	*50.00 FS	✓
54	1		*FRONT NO.PLATE WITH BOX	0.00	0.00	*30.00 FS	✓
55	1		*FRONT BUMPER RIVET	0.00	0.00	*30.00 FS	✓
56	1		*RADIATOR COOLANT	0.00	0.00	*30.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	48,457.00
+ Margin on L,N Items 10.00% (\$\$)	4,826.20
Total Parts (\$\$)	53,283.20

Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE & RENEW ROOF LINING	New	250.00 ^{150l}
2	TO REMOVE FOOR LINING AIR BAG,ALL SEAT BELT,STEERING AIR BAG,PASSENGER AIR BAG FOR RENEW ,REWIRE ,DIAGNOS,PROGRAMME & RESET AIR BAG SYSTEM	New	300.00 ^{200l}
3	TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM	New	150.00 ^{20l}
4	TO REMOVE & RENEW FRONT W/S GLASS & CONDUCT WATER LEAK TEST	New	150.00 ^{120l}
5	TO REMOVE AIR CON CONDENSER,PIPES & DRIER , VACUUM AND TO RECHARGE GAS	New	120.00 ^{100l}
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY & REWIRING	New	200.00 ✓
7	TO PUTTY AND SPRAY REPLACED PARTS	New	900.00 ^{800l}
8	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,000.00 ^{700l}
Gross Labour Cost (\$\$)			3,070.00

Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	024207
Policy No:	MPC23B00128300	Date of Loss:	20/10/2024
Vehicle Reg. No.:	SDK9977S	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KANNIAH MUKILAN	Contact No:	+6590235354
Driver:	KANNIAH MUKILAN		

Make/Model:	BMW 520I LED NAV, 2.0 (A)	Vehicle Reg. Date:	06/07/2018
Vehicle Colour:	BLUE		
Engine No:	13515127B48B20A	Chassis No:	WBAJA12020BJ19142
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 14

*Not Authored
17 Py @
Repair After Paint
Ex TBA*

Present Location: ALAN'S UNITED AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	53,283.20
Miscellaneous Items	0.00
Labour	3,070.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	56,353.20
+ GST 9.00% (S\$)	5,071.79
Nett Amount (S\$)	61,424.99

This claim is handled by: CHAN YEW SIAH

Generated using Merlimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	701J

Vehicle Details

Vehicle No.:	SDK9977S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Oct 2024
Vehicle Make:	B.M.W.
Vehicle Model:	520i LED NAV
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	13515127B48B20A
Chassis No.:	WBAJA12020BJ19142
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$47,763.00
Original Registration Date:	06 Jul 2018
First Registration Date:	06 Jul 2018
Transfer Count:	2
Actual ARF Paid:	\$58,869.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Jul 2028
PARF Rebate Amount:	\$38,264.00

Intended COE Rebate Details

COE Expiry Date:	05 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,000.00
COE Rebate Amount:	\$11,477.00
Total Rebate Amount:	\$49,741.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 22 Oct 2024

OK