

**Alan's United Auto Pte Ltd** (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER: **ECICS Limited (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	024207
Policy No:	MPC23B00128300	Date of Loss:	20/10/2024
Vehicle Reg. No.:	<b>SDK9977S</b>	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KANNIAH MUKILAN	Contact No:	+6590235354
Driver:	KANNIAH MUKILAN		

Make/Model:	BMW 520I LED NAV, 2.0 (A)	Vehicle Reg. Date:	06/07/2018
Vehicle Colour:	BLUE	Chassis No:	WBAJA12020BJ19142
Engine No:	13515127B48B20A		
Odometer:	0 KM		

Paint Type:	
Total Loss?	<b>NO</b>
Est. Duration of Repair (day)	14

*Not Authorized  
 11 Pny @ 34,000/-  
 Resurvey After Paint  
 Ex TRA*

Present Location: ALAN'S UNITED AUTO PTE LTD (HQ)

**COST OF CLAIMS**

	<b>Amount</b>
Parts	53,283.20
Miscellaneous Items	0.00
Labour	3,070.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>56,353.20</b>
<b>+ GST 9.00% (S\$)</b>	<b>5,071.79</b>
<b>Nett Amount (S\$)</b>	<b>61,424.99</b>

**This claim is handled by: CHAN YEW SIAH**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 24 Oct 2024)  
**Parts:** 143      BMW 520I LED NAV 2.0 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT WINDSCREEN GLASS	CM	0.00	0.00	*980.00 F	✓
2	1		*FRONT W/S GLASS MOULDING	NCL	0.00	0.00	*85.00 F	✓
3	1		*STEERING AIR BAG	Burn	0.00	0.00	*2,350.00 F	✓
4	1		*STEERING AIR BAG COIL SPRING	M	0.00	0.00	*1,260.00 F	✓
5	1		*PASSENGER AIR BAG	Burn	0.00	0.00	*1,750.00 F	✓
6	2		*FRONT AIR BAG SENSOR	M	0.00	0.00	*560.00 F	✓
7	1		*AIR BAG CONTROL UNIT	M	0.00	0.00	*1,460.00 F	✓
8	1		*FRONT DASHBOARD ASSY	Tn	0.00	0.00	*4,900.00 F	✓
9	1		*ROOF LINING	Nebrun	0.00	0.00	*1,900.00 F	✓
10	2		*ROOF LINING AIR BAG	Burn	0.00	0.00	*1,880.00 F	✓
11	2		*FRONT SEAT SAFTEY BELT	Tn	0.00	0.00	*2,940.00 F	✓
12	2		*FRONT SEAT SAFTEY BELT BUCKLE		0.00	0.00	*1,040.00 F	X
13	3		*REAR SEAT SAFTEY BELT	Tn	0.00	0.00	*1,980.00 F	✓
14	3		*REAR SEAT BELT BUCKLE		0.00	0.00	*780.00 F	X
15	1		*REAR BOOT BATTERY ACTUATOR	Act	0.00	0.00	*290.00 F	Z
16	1		*REAR BOOT BATTERY ACTUATOR COVER		0.00	0.00	*350.00 F	Z
17	1		*BONNET	Bn	0.00	0.00	*2,870.00 F	✓
18	2		*BONNET HINGE		0.00	0.00	*330.00 F	X
19	1		*BONNET LOGO	Nd	0.00	0.00	*125.00 F	✓
20	1		*BONNET INSULATOR	Sn	0.00	0.00	*410.00 F	X
21	2		*HEADLAMP	o/s cm	n/s mycm	0.00	*7,600.00 F	✓
22	2		*HEADLAMP PANEL			0.00	*660.00 F	Z
23	1		*FRONT SUPPORT TOP PANEL	Bu	0.00	0.00	*290.00 F	✓
24	1		*FRONT SUPPORT TOP PANEL COVER	CM	0.00	0.00	*280.00 F	✓
25	1		*FRONT SUPPORT CENTRE PANEL	R	0.00	0.00	*155.00 F	✓
26	1		*SUPPORT PANEL REAR BRACKET		0.00	0.00	*180.00 F	X
27	1		*FRONT V BAR	R	0.00	0.00	*112.00 F	✓
28	1		*FRONT REINFORCEMENT	R	0.00	0.00	*780.00 F	✓
29	2		*FRONT REINFORCEMENT TOP BRACKET	D/S	0.00	0.00	*18.00 F	✓
30	1		*FRONT BUMPER SPONGE	CM	0.00	0.00	*98.00 F	✓
31	1		*FRONT BUMPER INNER PARTS		0.00	0.00	*135.00 F	Z
32	1		*FRONT LOWER BEAM		0.00	0.00	*535.00 F	Z
33	2		*FRONT LOWER BEAM SIDE BRACKET		0.00	0.00	*140.00 F	X
34	1		*FRONT LOWER BEAM FRONT COVER		0.00	0.00	*195.00 F	Z
35	1		*FRONT BUMPER FASCIA	Bt/cm	0.00	0.00	*1,700.00 F	✓
36	1		*FRONT BUMPER CENTRE BRACKET		0.00	0.00	*142.00 F	X
37	2		*FRONT BUMPER SIDE INNER PART		0.00	0.00	*360.00 F	Z
38	2		*FRONT BUMPER SIDE RETAINER	o/s cm		0.00	*44.00 F	✓
39	1		*FRONT BUMPER LOWER GRILLE	CM	0.00	0.00	*175.00 F	✓
40	2		*FRONT BUMPER SIDE GRILLE	o/s cm	0.00	0.00	*378.00 F	✓
41	2		*FRONT BUMPER SIDE GRILLE CHROME	o/s cm	0.00	0.00	*270.00 F	✓
42	2		*FRONT BUMPER SIDE GRILLE INNER COVER	o/s cm	0.00	0.00	*170.00 F	✓
43	2		*FRONT GRILLE	CM	0.00	0.00	*420.00 F	✓
44	2		*FRONT BUMPER CENTRE PARKING SENSOR	mis	0.00	0.00	*440.00 F	✓
45	1		*AIR CON CONDENSER	Pu	0.00	0.00	*880.00 F	✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*RADIATOR ASSY			
47	1		*RADIATOR TOP GARNISH	0.00	0.00	<i>By</i> *1,350.00 F <i>2</i>
48	1		*AIR CON CONDENSER AIR VENT	0.00	0.00	<i>Sm</i> *130.00 F <i>X</i>
49	1		*AIR CON CONDENSER LOWER GUIDE	0.00	0.00	<i>cm</i> *155.00 F <i>2</i>
50	1		*RADIATOR FAN MOTOR	0.00	0.00	<i>Sm</i> *170.00 F <i>X</i>
51	1		*RADIATOR FAN COWLNG	0.00	0.00	<i>Sm</i> *1,580.00 F <i>X</i>
52	1		*FRONT W/S GLASS SEALANT	0.00	0.00	<i>nm</i> *480.00 F <i>X</i>
53	1		*ERP IU BRACKET	<i>nc</i> 0	0.00	<i>40w</i> *60.00 FS <i>✓</i>
54	1		*FRONT NO.PLATE WITH BOX	<i>m</i> 0	0.00	*25.00 FS <i>✓</i>
55	1		*FRONT BUMPER RIVET	0	0.00	<i>45n</i> *50.00 FS <i>✓</i>
56	1		*RADIATOR COOLANT	0	0.00	<i>nc</i> *30.00 FS <i>✓</i>
				0	0.00	<i>m</i> *30.00 FS <i>✓</i>

F=Franchise part. S=SpcNett.

Sub Total (S\$)	48,457.00
+ Margin on L,N Items 10.00% (S\$)	4,826.20
<b>Total Parts (S\$)</b>	<b>53,283.20</b>

Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REMOVE & RENEW ROOF LINING		150.00
2	TO REMOVE FOOR LINING AIR BAG,ALL SEAT BELT,STEERING AIR BAG,PASSENGER AIR BAG FOR RENEW ,REWIRE ,DIAGNOS,PROGRAMME & RESET AIR BAG SYSTEM	New	250.00
3	TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM	New	200.00
4	TO REMOVE & RENEW FRONT W/S GLASS & CONDUCT WATER LEAK TEST	New	150.00
5	TO REMOVE AIR CON CONDENSER,PIPES & DRIER , VACUUM AND TO RECHARGE GAS	New	120.00
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY & REWIRING	New	120.00
7	TO PUTTY AND SPRAY REPLACED PARTS	New	200.00
8	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	900.00
		New	700.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,070.00</b>

Alan's United Auto Pte Ltd/SDK9977S/24/10/2024 10:49. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >