



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 2

<b>Our Ref</b>	: UC1400
<b>Vehicle No.</b>	: SGQ3818R
<b>Make &amp; Model</b>	: HONDA HRV 1.5 LX CVT

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b><u>LABOUR</u></b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	
3	To perform anti-rust treatment on affected areas	90.00	
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	
5	To remove and refit rear seat compartment fitting, trimmings, garnish and etc	100.00	
6	To carried out repair and refit/replace of rear windscreen	100.00	
7	To remove and replace rear parking sensor	100.00	
<b>Labour Total :</b>		<b>2680.00</b>	
<b>TOTAL (PARTS &amp; LABOUR):</b>		<b>8368.60</b>	