



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1400		Page No. 1		
Vehicle No. : SGQ3818R				
Make & Model : HONDA HRV 1.5 LX CVT				
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear windscreen moulding <i>new</i>		160.00	144
1	Tail lamp RH <i>ca</i>		525.00	419.42
1	Boot lid lamp RH <i>ca</i>		295.00	256.40
1	Boot lid <i>bt</i>		1050.00	
1	Boot lid top garnish <i>ca</i>		190.00	
1	Boot lid logo badge <i>new</i>		16.00	
1	Boot lid emblem "HR-V" <i>new</i>		17.00	
1	Boot lid emblem "i-VTEC" <i>new</i>		18.00	
2	Boot lid hinge RH/LH @ 2" \$45 <i>ca</i>		90.00 X	
1	Boot lid weatherstrip <i>de</i>		108.00	80.77
1	Boot lid stopper RH <i>new</i>		11.00	
1	Boot lid cover RH <i>ca</i>		14.00 X	
1	Boot lid trim board <i>fix</i>		149.00 X	
1	Boot lid trim board handle <i>ca</i>		19.00 X	
1	Rear side bumper RH <i>cut</i>		94.00	
1	Rear side bumper retainer RH <i>fix</i>		19.00 X	
1	Rear bumper <i>de</i>		3464.00	508.50
1	Rear bumper stopper RH <i>ca</i>		13.00	
1	Rear reflector RH <i>fix</i>		190.00 X	
1	End panel top garnish <i>fix</i>		67.00 X	
1	End panel <i>repair</i>		408.00 Rx	
1	Rear fender RH (repair refer to labour)		0.00	
SPECIAL NETT ITEMS				
1	Rear windscreen sealant <i>new</i>		6917.00	<i>80</i>
1	End panel sealant <i>fix</i>		-1383.40	<i>60.00</i>
1	Rear carplate with holder <i>ca</i>		5533.60	<i>35.00</i>
Part Items Total: -20%			6917.00	
			-1383.40	
			5533.60	
SN Items Total:			155.00	
Total Parts:			5688.60	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : UC1400		Page No. 2	
Vehicle No. : SGQ3818R			
Make & Model : HONDA HRV 1.5 LX CVT			
S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
LABOUR			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	500 500 + 100 = 600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	400 300 + 200 = 500
3	To perform anti-rust treatment on affected areas	90.00	40
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	40
5	To remove and refit rear seat compartment fitting, trimmings, garnish and etc	100.00	50, Xnn
6	To carried out repair and refit/replace of rear windscreen	100.00	1330
7	To remove and replace rear parking sensor	100.00	50
Labour Total :		2680.00	
TOTAL (PARTS & LABOUR):		8368.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2254.47

40.00

1330.00

3624.47

Rahul

Hp 9000068

5 days

45 P/P

12/11/24

Res after repair