


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 28.10.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNH6792A**
MODEL : **TOYOTA VELLFIRE**
DATE OF ACCIDENT : 22.10.2024
TIME OF ACCIDENT : 21:45 HOURS

Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delud</i>	1	\$ 1,699.00	\$ 1,699.00 <i>1150</i>
2	REAR BUMPER REFLECTOR LH <i>Curled</i>	1	\$ 98.00	\$ 98.00
3	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 45.00	\$ 45.00
4	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 95.00	\$ 190.00
5	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	2	\$ 95.00	\$ 190.00
6	REAR BUMPER SIDE INNER GARNISH LH <i>Delud</i>	1	\$ 158.00	\$ 158.00
7	REAR BUMPER SENSOR LH <i>Delud</i>	2	\$ 398.00	\$ 796.00 <i>398</i>
8	REAR BUMPER SENSOR HOLDER LH <i>new</i>	4	\$ 45.00	\$ 180.00 <i>45</i>
9	REAR BUMPER BRACKET LH <i>new</i>	1	\$ 58.00	\$ 58.00
10	TAILLAMP LH <i>new</i>	1	\$ 825.60	\$ 825.60
11	REAR CORNER PANEL LH <i>Delud</i>	1	\$ 368.10	\$ 368.10
12	REAR CORNER PANEL RETAINER LH <i>new</i>	1	\$ 142.10	\$ 142.10
13	REAR FENDER COWLING LH <i>new</i>	1	\$ 172.00	\$ 172.00
14	REAR AIR VENT LH <i>new</i>	1	\$ 115.00	\$ 115.00
15	REAR AIR VENT SIDE COVER LH <i>new</i>	1	\$ 35.00	\$ 35.00

TOTAL PRICE \$ 5,071.80
LESS 25% \$ 1,267.95
SUB TOTAL PRICE \$ 3,803.85

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNH6792A**
 MODEL : **TOYOTA VELLFIRE**
 DATE OF ACCIDENT : 22.10.2024
 TIME OF ACCIDENT : 21:45 HOURS

2	REAR BUMPER LOWER LID (SPECAIL TYPE)	1	\$ 1,800.00	\$ 1,800.00	1000
3	REAR BUMPER SIDE UPPER GARNISH RH CLIP (SET)	1	\$ 30.00	\$ 30.00	+
4	REAR BUMPER SIDE INNER GARNISH CLIP (SET)	1	\$ 30.00	\$ 30.00	20
5	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 30.00	\$ 30.00	+
6	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00	+
7	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00	+

1050 TOTAL \$ 2,040.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	500
3	TUFF COAT	\$ 250.00	850
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x
5	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$3,760.00

TOTAL PARTS COST : \$ 5,843.85
 TOTAL LABOUR COST : \$ 3,760.00
 TOTAL REPAIR COST : \$ 9,603.85

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

LKK Auto Consultants hence notify
 the Receiver of the following:
 • To resurvey before the repair work
 • To display damaged parts during the repair
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian L
 2/5 28/10/24

03 days.

total 3523.07

4/5 : 2.8K

2.8K