

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate No. _____

OD / TP / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No. _____

Claim No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remarks: There had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNH 6792A Yr Regn: 2019, MarchType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vellfire C.D. 3456Colour: Black A/C: Insured / Std / NI / NASp. Reading: 176375 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GGH 300032119

Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil S/Rim / STD A/Rim orTyre Size: F: 235/50R19R: 235/50R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/10/24Survey held at WD Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP 1st Cap.COE ExpiryEstimate given during : Yes (✓)
1st Survey : No ()MV : 175KPV : 82.3KNett. 92.7K908K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Addl Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)

Photos

Others

Report Format: _____

Report Date/Time/Place


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 28.10.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNH6792A**
MODEL : **TOYOTA VELLFIRE**
DATE OF ACCIDENT : 22.10.2024
TIME OF ACCIDENT : 21:45 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delud</i>	1	\$ 1,699.00	\$ 1,699.00
2	REAR BUMPER REFLECTOR LH <i>Curled</i>	1	\$ 98.00	\$ 98.00
3	REAR BUMPER TOW HOOK COVER <i>new</i>	1	\$ 45.00	\$ 45.00
4	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 95.00	\$ 190.00
5	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	2	\$ 95.00	\$ 190.00
6	REAR BUMPER SIDE INNER GARNISH LH <i>Delud</i>	1	\$ 158.00	\$ 158.00
7	REAR BUMPER SENSOR LH <i>Delud</i>	2	\$ 398.00	\$ 796.00
8	REAR BUMPER SENSOR HOLDER LH <i>new</i>	4	\$ 45.00	\$ 180.00
9	REAR BUMPE BRACKET LH <i>new</i>	1	\$ 58.00	\$ 58.00
10	TAILLAMP LH <i>new</i>	1	\$ 825.60	\$ 825.60
11	REAR CORNER PANEL LH <i>Delud</i>	1	\$ 368.10	\$ 368.10
12	REAR CORNER PANEL RETAINER LH <i>new</i>	1	\$ 142.10	\$ 142.10
13	REAR FENDER COWLING LH <i>new</i>	1	\$ 172.00	\$ 172.00
14	REAR AIR VENT LH <i>new</i>	1	\$ 115.00	\$ 115.00
15	REAR AIR VENT SIDE COVER LH <i>new</i>	1	\$ 35.00	\$ 35.00

TOTAL PRICE \$ 5,071.80
LESS 25% \$ 1,267.95
SUB TOTAL PRICE \$ 3,803.85

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00

Adrian L
2/5 28/10/24
03 days