



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: AINI		Ref: CS/FCI24100491/Tqp3e2(N) Date: 15/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9860H	Veh. Inspected	SNK 3395S
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24009460MFCT	Excess (\$)	0.00
Assign From	AINI	Assign Date	28/10/2024
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 118i	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WBA7K320705R76557	Colour	ORANGE
Odometer	11671 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/40 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/40 R18	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	25/10/2024	Inspection Date	30/10/2024
Survey held at	11 KUNG CHONG ROAD, S(159147)		
Repairer	TRANS EUROKARS PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	