

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : VJW 8550

Acc: 24.10.24

Not Authorized  
11 Amp @ 9500h  
Recovery After Paim  
12 days

S/N	Parts Description	Unit Price	Amt	
		Ry	\$659.00	✓
1	Rear bootlid	na	\$39.20	✓
2	Rear bootlid emlem	na	\$29.60	✓
3	Rear bootlid Civic emblem	na	\$28.60	✓
4	Rear bootlid I-Vtec emblem	dis	\$225.30	✓
5	Rear bootlid relector X 2	na	\$105.30	X
6	Rear bootlid insulator	na	\$165.00	✓
7	Rear bootlid lock	dis	\$108.20	✓
8	Rear bootlid rubber	dis	\$192.60	✓
9	Rear bootlid No.plate garnish	dis	\$366.50	✓
10	Taillamp assy X 2	R	\$205.00	X
11	Taillamp inner panel X 2	Ry	\$566.10	✓
12	Rear bumper assy	CM	\$25.50	✓
13	Rear bumper retainer X 2	Ry	\$225.00	✓
14	Rear bumper reinforcement	su	\$86.00	X
15	Rear bumper reflector X 2	Ry	\$430.80	✓
16	Rear end panel	mg	\$108.60	✓
16	Rear end panel top garnish	R	\$1,256.20	X
17	Rear spare tyre panel	CM	\$196.80	✓
18	Rear spare tyre panel top cover	Bu	\$981.80	✓
19	Rear fener LH	su	\$304.20	X
20	Rear fender inner garnish LH	na	\$121.60	✓
21	Rear windscreen mldg	Ry	\$745.20	✓
22	Bonnet	R	\$84.20	X
23	Bonnet hinge X 2	R	\$105.40	X
24	Bonnet lock	reform	\$53.60	✓
25	Bonnet inner rubber	su	\$165.40	X
26	Bonnet insulator	CM	\$175.20	✓
27	Front grille	CM	\$186.30	✓
28	Front grille top chrome	na	\$38.10	✓
29	Front grille emblem	mg	\$1,551.20	✓
30	Headlamp X 2	dis	\$58.20	✓
31	Headlamp lower bracket X 2	na	\$95.60	✓
32	Headlamp top chrome X 2	R	\$606.00	X
33	Front support panel	Bu / mg	\$617.50	✓
34	Front bumper assy	Ry	\$365.10	✓
35	Front bumper reinforcement	\$30.10	\$60.20	X
36	Front retainer X 2	su	\$108.20	X
37	Front bumper lower grille			

## Special Nett

1 Bootlid insulator clips

na \$60.00 X

208

- 2 Rear bumper clips
- 3 Rear windscreen sealant
- 4 Bonnet insulator clips
- 5 Front grille clips
- 6 Front bumper clips
- 7 Rear and front No.plate

na \$50.00 ✓  
 na \$80.00 405m ✓  
 na \$50.00 X  
 na \$40.00 ✓  
 na \$50.00 ✓  
 cm \$120.00 805m ✓

### Labour

- 1 To cut/weld and remove and refit damaged parts
- 2 To spray paint on affected parts
- 3 To remove and refit rear reverse sensor
- 4 To remove and refit rear garnishes and etc.
- 5 Tuff coat on affected parts
- 6 To check wiring
- 7 To remove and refit air-con and refill gas
- 8 To remove and refit rear windscreen

\$1,400.00 1200

\$2,000.00 1600

\$120.00 50

\$200.00 100

\$250.00 120

\$80.00 40

na \$200.00 X

\$200.00 120

\$4,450.00

Page 2

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: