

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLZ380Z

Not Authorized

11 Sep 8

Re survey After Painting

Ex TRA

6 days

No.	Qty	List Items	
1	1	Front bumper	\$ CM 791.35 ✓
2	2	Front bumper fog lamp	\$ Pn 941.60 X
3	2	Front bumper side retainer	old \$ CM 277.90 ✓
4	2	Front bumper top side rubber seal	\$ Pn 70.40 ✓
5	1	Front bumper inner foam	\$ CM 156.85 ✓
6	1	Front bumper inner reinforcement	\$ 596.80 ?
7	1	Front bumper centre top black garnish	\$ CM 148.60 ✓
8	1	Front bumper lower skirting	\$ Pn 285.30 X
9	2	Front bumper lower skirting side cover	\$ Pn 118.00 X
10	1	Front grille	\$ CM 280.80 ✓
11	1	Front grille "S" emblem	\$ Pn 65.50 ✓
12	2	Headlamp	\$ CM 4,381.30 ✓
13	2	Headlamp black trim	\$ CM 316.00 ✓
14	1	Front bonnet	\$ Pn 1,846.10 ✓
15	1	Front bonnet top air scoop	\$ Pn 346.70 ✓
16	1	Front bonnet top "MINI" logo	\$ Pn 65.10 ✓
17	1	Front bonnet lock	\$ Pn 107.65 ✓
18	2	Front bonnet hinge	\$ 192.50 ?
19	1	Front bonnet insulator	\$ 201.10 ?
20	1 set	Front bonnet insulator clips	\$ Pn 60.00 ✓
21	1	Front support panel	\$ 782.00 ?
22	1	Air con condenser	\$ 1,068.80 ?
23	1	Radiator	\$ 941.60 ?
24	2	Front wheel arch black garnish	\$ 308.20 ?
25	2 set	Front wheel arch black garnish clips	\$ Pn 80.00 ✓
26	1	Front wiper garnish top	\$ 193.00 ?
27	1	Front wiper garnish lower	\$ 193.00 ?

LKK Auto Consultants hence notify the Repairer of the following less 5%
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation

Special Nett Items
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

- 28 1 Front number plate
 29 1 btl Radiator coolant

\$ 14,816.15
 \$ 740.81
 Total : \$ 14,075.34
 \$ Pn 80.00 X
 \$ 50.00 ?
 Total : \$ 130.00

Labour

- 1 Labour Charges for remove/refit, cutting/welding and replacement of damages. \$ 1,000.00 60d
 2 To putty and spray Spray Paintings charges. \$ 1,000.00 80d
 3 To remove, refit A/c condenser, radiator and etc..., and refill air con gas. \$ 150.00 10d
 4 To check wirings and lightings. \$ 40.00 2d

5 To supply and apply anti rust treatment

Total : \$ ~~142~~ 80.00 X
\$ 2,270.00

Total Parts and Labour : \$ 16,475.34