

ASS. REC. BY:

REF:

CS/III24100493/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: D21MPC0007390

Policy No. MPC2024D0012781

Claims No.

Sum Insured:

Excess:

750

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL 83802

Yr Regn:

03, 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mini Coupe S c.c. 1994

Colour

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

159954

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMNLN720602G79636

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

25/10/24

D.O.I.

29/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Bumper jammed

15/11

41 Lpm @ 13, Fuel Cuts

(red 5804.56, 29%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

F. 125

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	26/10/2024 11:26 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	25/10/2024 16:30 (SGT)
Exact Location of Accident	TPE, Singapore
Additional Location Information	TOWARDS CTE/SLE AT PUNGGOL RD EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ380Z
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHOW CHENG HUA
NRIC No	SXXXX193F
Email Address	chenghua@hotmail.com
Mobile Phone No	(Phone) +65-81338699
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mini
Model	Clubman
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1994
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D21MPC0007390_03

DRIVER

Name of Driver	CHOW CHENG HUA
NRIC No	SXXXX193F
Date Of Birth	24/09/1990
Occupation	Indoor
Driving Pass Date	26/08/2009
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	15 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81338699
Alt. Phone Number	-
Email Address	chenghua@hotmail.com
Address	999B BUANGKOK CRESCENT
Address complement	#08-757
Postcode	532999
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED SKETCH PLANS

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ4873K
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

26/10/24

10.00am

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NR/CND card)

Sketch Plan

R = SL2380Z
B = YQ4873X

1

Describe Circumstance of the Accident

~~105~~ Front Vehicle 4YQ4873E e-brake and I was not able to
 Stop in time and I hit the rear. No injuries, private settled
 with the driver and agreed to no compensation.

Declaration

I/We declare the foregoing particulars are true in every respect.

[Signature] 26/10/24
 10:00am

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
 / Date & Time



Witnessed by Reporting Centre Personnel
 (Name as in NRIC/ID card)

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLZ380Z

Not Authorized

11/11/8

Recovery After Painting

Ex TRA

6 days

No.	Qty	List Items		
1	1	Front bumper	\$ CM	791.35 ✓
2	2	Front bumper fog lamp	\$ Pn	941.60 X
3	2	Front bumper side retainer	old \$ CM	277.90 ✓
4	2	Front bumper top side rubber seal	\$ Pn	70.40 ✓
5	1	Front bumper inner foam	\$ CM	156.85 ✓
6	1	Front bumper inner reinforcement	\$	596.80 ?
7	1	Front bumper centre top black garnish	\$ CM	148.60 ✓
8	1	Front bumper lower skirting	\$ Pn	285.30 X
9	2	Front bumper lower skirting side cover	\$ Pn	118.00 X
10	1	Front grille	\$ CM	280.80 ✓
11	1	Front grille "S" emblem	\$ Pn	65.50 ✓
12	2	Headlamp	\$ CM	4,381.30 ✓
13	2	Headlamp black trim	\$ CM	316.00 ✓
14	1	Front bonnet	\$ Pn	1,846.10 ✓
15	1	Front bonnet top air scoop	\$ Pn	346.70 ✓
16	1	Front bonnet top "MINI" logo	\$ Pn	65.10 ✓
17	1	Front bonnet lock	\$ Pn	107.65 ✓
18	2	Front bonnet hinge	\$	192.50 ?
19	1	Front bonnet insulator	\$	201.10 ?
20	1 set	Front bonnet insulator clips	\$ Pn	60.00 ✓
21	1	Front support panel	\$	782.00 ?
22	1	Air con condenser	\$	1,068.80 ?
23	1	Radiator	\$	941.60 ?
24	2	Front wheel arch black garnish	\$	308.20 ?
25	2 set	Front wheel arch black garnish clips	\$ Pn	80.00 ✓
26	1	Front wiper garnish top	\$	193.00 ?
27	1	Front wiper garnish lower	\$	193.00 ?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Special Nett Items

28	1	Front number plate	\$ Pn	80.00 X
29	1 btl	Radiator coolant	\$	50.00 ?
Total :			\$	130.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$	1,000.00	600
2	To putty and spray Spray Paintings charges.		\$	1,000.00	800
3	To remove, refit A/c condenser, radiator and etc..., and refill air con gas.		\$	150.00	100
4	To check wirings and lightings.		\$	40.00	20

5 To supply and apply anti rust treatment

Total : \$ ~~162~~ 80.00 X
\$ 2,270.00

Total Parts and Labour : \$ 16,475.34

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SLZ380Z

Not Authorized
11/11/813, 700h
Running After Pains
Ex TBA

6 days

No.	Qty	List Items	
1	1	Front bumper	\$ CM 791.35 ✓
2	2	Front bumper fog lamp	\$ Pu 941.60 X
3	2	Front bumper side retainer	old \$ CM 277.90 ✓ + 138.95
4	2	Front bumper top side rubber seal	\$ Pu 70.40 ✓
5	1	Front bumper inner foam	\$ CM 156.85 ✓
6	1	Front bumper inner reinforcement	\$ Pu 596.80 ✓
7	1	Front bumper centre top black garnish	\$ CM 148.60 ✓
8	1	Front bumper lower skirting	\$ Pu 285.30 X
9	2	Front bumper lower skirting side cover	\$ Pu 118.00 X
10	1	Front grille	\$ CM 280.80 ✓
11	1	Front grille "S" emblem	\$ Pu 65.50 ✓
12	2	Headlamp	\$ CM 4,381.30 ✓
13	2	Headlamp black trim	\$ CM 316.00 ✓
14	1	Front bonnet	\$ Pu 1,846.10 ✓
15	1	Front bonnet top air scoop	\$ M/I 346.70 ✓
16	1	Front bonnet top "MINI" logo	\$ Pu 65.10 ✓
17	1	Front bonnet lock	\$ Pu 107.65 ✓
18	2	Front bonnet hinge	old \$ Pu 192.50 ✓ + 96.25 N
19	1	Front bonnet insulator	Not in \$ Pu 201.10 ✓
20	1 set	Front bonnet insulator clips	\$ Pu 60.00 ✓
21	1	Front support panel	\$ Pu 782.00 ✓
22	1	Air con condenser	\$ Pu 1,068.80 ✓
23	1	Radiator	\$ Pu 941.60 ✓
24	2	Front wheel arch black garnish	\$ M/I CM 308.20 ✓
25	2 set	Front wheel arch black garnish clips	\$ Pu 80.00 ✓
26	1	Front wiper garnish top	\$ Pu 193.00 ✓
27	1	Front wiper garnish lower	\$ Defun 193.00 ✓
			\$ 14,816.15
Less 5%			\$ 740.81
Total :			\$ 14,075.34

Special Nett Items

28	1	Front number plate	\$ Pu 80.00 X
29	1 btl	Radiator coolant	\$ Pu 50.00 ✓
Total :			\$ 130.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00 600
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 800
3	To remove, refit A/c condenser, radiator and etc..., and refill air con gas.	\$ 150.00 100
4	To check wirings and lightings.	\$ 40.00 20

5

To supply and apply anti rust treatment

Total : \$ ¹⁴² 80.00 X
\$ 2,270.00

Total Parts and Labour : \$ 16,475.34

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

04.11.2024

SUPPLEMENTARY REPAIR ESTIMATE FOR Mini Clubman - SLZ 380 Z

<u>List Items</u>			
1 pc.	Exhaust manifold	CM \$	825.00 ✓
2 pcs.	Headlamp bracket (\$220/pc)	B \$	440.00 ✓
1 pc.	V Strut panel	B \$	183.00 ✓
1 pc.	Air duct	CM \$	380.00 ✓
1 set.	Front bonnet moulding	nd \$	236.65 ✓
2 pcs.	Front bonnet lock bracket (\$122/pc)	dir \$	244.00 ✓
1 pc.	Front bumper inner reinforcement cover	ngum \$	320.00 ✓
2 pcs.	Front bumper inner part LH & RH (\$280/pc)	\$B \$	560.00 ✓
			\$ 3,188.65
		Less 5%	\$ 159.43
			<u>\$ 3,029.22</u>