

源 摩 哆 廠

GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SL2380Z

No.	Qty	List Items		
1	1	Front bumper	\$	791.35
2	2	Front bumper fog lamp	\$	941.60
3	2	Front bumper side retainer	\$	277.90
4	2	Front bumper top side rubber seal	\$	70.40
5	1	Front bumper inner foam	\$	156.85
6	1	Front bumper inner reinforcement	\$	596.80
7	1	Front bumper centre top black garnish	\$	148.60
8	1	Front bumper lower skirting	\$	285.30
9	2	Front bumper lower skirting side cover	\$	118.00
10	1	Front grille	\$	280.80
11	1	Front grille "S" emblem	\$	65.50
12	2	Headlamp	\$	4,381.30
13	2	Headlamp black trim	\$	316.00
14	1	Front bonnet	\$	1,846.10
15	1	Front bonnet top air scoop	\$	346.70
16	1	Front bonnet top "MINI" logo	\$	65.10
17	1	Front bonnet lock	\$	107.65
18	2	Front bonnet hinge	\$	192.50
19	1	Front bonnet insulator	\$	201.10
20	1 set	Front bonnet insulator clips	\$	60.00
21	1	Front support panel	\$	782.00
22	1	Air con condenser	\$	1,068.80
23	1	Radiator	\$	941.60
24	2	Front wheel arch black garnish	\$	308.20
25	2 set	Front wheel arch black garnish clips	\$	80.00
26	1	Front wiper garnish top	\$	193.00
27	1	Front wiper garnish lower	\$	193.00
			\$	14,816.15
			Less 5%	\$ 740.81
			Total :	\$ 14,075.34

Special Nett Items

28	1	Front number plate	\$	80.00
29	1 btl	Radiator coolant	\$	50.00
			Total :	\$ 130.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,000.00
2	To putty and spray Spray Paintings charges.	\$	1,000.00
3	To remove, refit A/c condenser, radiator and etc..., and refill air con gas.	\$	150.00
4	To check wirings and lightings.	\$	40.00