

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133/62717433 FAX:62745715

ESTIMATE REPAIR

Pg 1

Liberty Insurance Pte Ltd

Date: 28.10.2024

Owner's Name : Jacquelyn Goh

Vehicle No : SMM9874M

Claim Type: Third Party Claim

Vehicle Make & Model : Toyota Esquire Hybrid 1.8 GI CVT

Chassis No: ZWR800391574

Registration Date : 22 Jul 2019 (YOM 2019) COE Expiry Date 21 Jul 2029

DOA: 27.10.2024

No	Description	Unit	List (\$)
1	REAR TAILGATE <i>bt</i>	1	\$ 1,909.70
2	REAR TAILGATE ABSORBER <i>X</i>	2	\$ 597.20
3	REAR TAILGATE GLASS MOUNDING <i>m</i>	SET	\$ 195.00
4	REAR TAILMGATE EMBLEM "ESQUIRE" <i>m</i>	1	\$ 100.00
5	REAR TAILGATE LOCK <i>?</i>	1	\$ 715.88
6	REAR TAILGATE TRIM BOARD <i>?</i>	1	\$ 720.85
7	REAR TAILGATE WEATHERSHIP <i>?</i>	1	\$ 360.50
8	REAR BUMPER <i>de</i>	1	\$ 920.90
9	REAR BUMPER SIDE RETAINER *Short <i>?</i>	1 <i>X</i>	\$ 230.00
10	REAR BUMPER SIDE RETAINER * Long <i>?</i>	1 <i>X</i>	\$ 270.00
11	REAR BUMPER REFLECTOR (RH) <i>?</i> / LH <i>X</i>	1 <i>X</i>	\$ 190.00
12	REAR END PANEL <i>?</i>	1	\$ 770.50
13	REAR END PANEL GARNISH <i>?</i>	1	\$ 340.40
14	REAR SPRAE TYRE PANEL <i>X</i>	1	\$ 800.90
15	REAR SPARE TYRE CARMAT <i>X</i>	1	\$ 495.00
16	REAR BUMPER SENSOR <i>?</i>	2	\$ 580.00
17	REAR BUMPER SENSOR HOUSING <i>m</i>	2	\$ 130.00
18	REAR SENSOR ANTENNA <i>?</i>	1	\$ 285.75
19	REAR BUMPER CENTER BRACKET <i>?</i>	1	\$ 320.00

Total (A) : \$ 9,932.58

Less 25% \$ 2,483.15

Total: \$ 7,449.43

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/62717433 FAX:6274571

Pg 2

DOA: 27.10.2024

[illegible]

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/62717433 FAX:62745715

Pg 3

[illegible]