

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24100496/Aqh3m4(N)
	75 BRAS BASAH R		Date:	06/02/2025	
	ATTN: MARCUS XI	AO		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 755P	Veh. Inspected	t	SNC 1054G
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1301694-001	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		28/10/2024
2. Vehicle Particulars & Condition					
	Make & Model	SUZUKI SWIFT	c.c		998
	Engine No.	HIDDEN	Year of Reg.		2019
	Chassis No.	JSAAZC13S00300171	Colour		RED
	Odometer	87740 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	185/55R16	BRIDGESTONE		6 mm
	L/H Front Tyre	185/55R16	BRIDGESTONE		6 mm
	R/H Rear Tyre	185/55R16	BRIDGESTONE		6 mm
	L/H Rear Tyre	185/55R16	BRIDGESTONE		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
	Dr.(W), (OEO OEE DE	Trues.			1.0
5. General Information					
	Accident Date	24/10/2024	Inspect Date /	Time	06/11/2024 (04:22 PM)
	Survey held at	KT MOTORWERK			
		3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
					<u> </u>