

YEW HOK AUTO SERVICES

522 Bedok North Ave 1, #11-310, Singapore 460522

H/P: 8285 7623

Email: yhlee@outlook.sg

Not Authorized
in
Merus
29/10/24
4/5 & 2200
Telephone: 8285 7623
4 days

Vehicle number: SND8999D

Vehicle Made & Model: TOYOTA AXIO

Qty	List Items		Amount \$
1	Front bumper	De/Toin	861.90 ✓
1	Front bumper sponge	11	180.63 X
1	Front bumper reinforcement	11	477.73 X
2	Front bumper side retainers - L/R @ 86.55	MS bent	173.10 PC
1	Front fender - LH	R	731.66 X
1	Front fender inner shield	11	181.43 X
1	Front grille	11	481.93 X
1	Front headlamp - LH	Che	1,260.90 ✓
1	Front support panel	R	831.10 X
1	Air cleaner intake hose	11	191.60 X
Sub-total			5,371.98
Less 25%			1,343.00
Total List			4,028.99

Special Nett Items

1 set	Front bumper clip	11	50.00 405/11
1 set	Front fender inner shield clip	11	60.00 X
Special Nett Items			110.00

Labour charges

To respray undercoating	11	50.00 X
To check front electrical wiring		50.00 20
To respray painting and etc		800.00 450
Panel beating, cut, weld remove & replacing above parts		800.00 600
Total Labour		1,700.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

5,838.99

LKK Auto Consultants hence notify
the Repairer of the following:

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insu

Page 1 of 1

Acknowledged by Repairer

Signature:

Date:

P-2209-35
252
1657.01
40
1070
2767.01
202
2723