



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100498/Uqh3m4
75 BRAS BASAH ROAD	Date:	26/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 963E	Veh. Inspected	SJA 8877K
Policy No.	-	Coverage	0
Claim No.	MT/1301513-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	29/10/2024

### 2. Vehicle Details

Make & Model	MERCEDES BENZ GLC300 SPORT	C.C	1991
Engine No.	26492030226900	Year of Reg.	15/07/2020
Chassis No.	WDC2539842F745764	Colour	GREY
Odometer	97640 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/60R18	PIRELLI	6
L/H Front Tyre	235/60R18	PIRELLI	6
R/H Rear Tyre	235/60R18	PIRELLI	6
L/H Rear Tyre	235/60R18	PIRELLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	25/10/2024	Inspection Date	30/10/2024 (10:55)
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days