

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 # 01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email : shawn7530@hotmail.com

not Authorized
has
Mars
30/10/24
4/5 \$3100
2 days
Cuba ph. After mp.

01 NOVEMBER 2024

Vehicle No: SJA8877K

Model : MERCEDES BENZ GLC300

QTY	DESCRIPTION	AMOUNT
1	Rear Tailgate	11 \$3668.00 X
1	Rear Tailgate Logo	11 \$169.90 X
1	Rear Tailgate "GLC300" emblem	11 \$120.00 X
1	Rear Tailgate "4 MATIC" emblem	11 \$88.00 X
1	Rear Bumper	1512.32 cut/ton \$2485.95
1	Rear Bumper Lower	1100.00 cut/ton \$1879.10
2	Rear Bumper Brackets	11 \$140.00 X
1	Rear Bumper Lower Spoiler	cut/ton \$873.40
1	Rear Bumper Reinforcement	su \$650.00 X
2	Rear Bumper Side Retainers	11 \$190.00 X
6	Rear Bumper PDC Sensors	su \$1920.00 X
2	Rear Bumper Reflector	11 \$88.00 X
1	Control Module for Park Assistant Kit	11 \$685.00 X
2	Rear Exhaust Mountings	11 \$120.00 X
2	Rear Exhaust Chrome Tail Pipes	su \$500.00 X
		\$13,577.35
Less 5% 102		\$678.87
		\$12,898.48

Special Nett Items

1	Rear Bumper Clip (1 set)	111	\$120.00 50
			<hr/>
			\$120.00

Labour Charges

To Remove, Replaced Damaged Lamps and check up Rear Wiring		\$80.00 20
To Remove & Refit Inner Garnishes	111	\$180.00 X
To Remove & Refit Rear Reverse Sensor		\$200.00 30
To Transfer Rear Tailgate Mechanism and wiring assembly	111	\$80.00 X
To Apply undercoating	111	\$200.00 X
Panel Beating		\$1200.00 300
To Re-Spray Painting on the affected areas		\$1200.00 400
		<hr/>
		\$3140.00

Grand Total	\$16,158.48
--------------------	--------------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: