

CARSMITH PRIVATE LIMITED

PREMIER@8 KAKI BUKIT AVE 4 #04-35 Singapore 415875

Tel: 9091 0000

VEHICLE NO: SNR9137U

MAKE & MODEL: BYD E6

DOA: 26.10.2024

CLAIM TYPE: TP CLAIM

Not Authorized
for
works

29/10/24

1/5 @ 13,100

10 days

car photo attached

KKK Auto Consultants hence notify

Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR BUMPER	1	\$ 1,850.00	Dis ✓
REAR BUMPER LOWER LIP	1	\$ 958.00	Dis ✓
REAR BUMPER RETAINER LH	1	\$ 112.00	MA ✓
REAR BUMPER RETAINER RH	1	\$ 112.00	17 X
REAR BUMPER BRACKET LH	1	\$ 87.00	Int ✓
REAR BUMPER BRACKET RH	1	\$ 87.00	17 X
REAR BUMPER GRILLE BAR LH	1	\$ 85.00	NF X
REAR BUMPER GRILLE BAR RH	1	\$ 85.00	NF X
REAR BUMPER GRILLE BAR CENTER	1	\$ 124.00	Dis ✓
REAR REFLECTOR LH	1	\$ 198.00	CRA ✓
REAR REFLECTOR LH	1	\$ 198.00	Repair X
REAR REFLECTOR CENTRE	1	\$ 425.00	CRA ✓
REAR FENDER INNER SHIELD LH	1	\$ 528.00	Torn ✓
REAR FENDER INNER TRIM LH	1	\$ 852.00	Dis ✓
REAR END PANEL INNER TRIM	1	\$ 758.00	MS X
REAR WHEEL GARNISH LH	1	\$ 1,050.00	Dis/CRA ✓
REAR END PANEL	1	\$ 852.00	Solyon ✓
REAR END PANEL TOP GARNISH	1	\$ 287.00	Tw ✓
REAR REINFORCEMENT	1	\$ 852.88	Dis ✓
REAR REINFORCEMENT BRACKET	2	\$ 352.00	NS X
SPARE TYRE SPONGE	1	\$ 247.00	Torn ✓
SPARE TYRE HOLDER Top board	1	\$ 425.00	waxed ✓
THIRD BRAKE LAMP	1	\$ 327.00	17 X
REAR WINDSCREEN	1	\$ 857.00	17 X
REAR WINDSCREEN MOULDING	1	\$ 472.00	17 X
WIPER	1	\$ 135.00	17 X
WIPER MOTOR	1	\$ 575.00	17 X
TAILGATE	1	\$ 3,048.70	3048.70 ✓
TAILGATE GARNISH	1	\$ 652.00	CRA ✓
TAILGATE LOCK	1	\$ 578.00	rev/17m ✓
TAILGATE WEATHERSTRIP	1	\$ 373.00	Tw ✓
TAILGATE HINGE	2	\$ 176.00	17 X
TAILGATE LAMP CENTRE	1	\$ 1,254.00	CRA ✓
TAILGATE LOGO	1	\$ 108.00	Tw ✓
TAILGATE EMBLEM 'GAC AION Y PLUS'	1	\$ 108.00	Tw ✓
TAILGATE CHROME MOULDING	1	\$ 345.00	17 X
TAILGATE INNER TRIM BOARD	1	\$ 358.00	Dis/Torn ✓
TAILGATE DAMPER LH	1	\$ 850.00	17 X

1st Rear PDC sensor wire 680	1	\$ 850.00	CRG / Torn /
TAILGATE AUTO MOTOR	1	\$ 1,850.00	11 X
TAILLAMP LH 702	1	\$ 783.00	CRG /
TAILLAMP RH 702	1	\$ 783.00	CRG /
TAILLAMP BRACKET LH	1	\$ 275.00	NS X
TAILLAMP BRACKET LH	1	\$ 275.00	NS X
TAILLAMP CHROME MOULDING LH	1	\$ 175.00	11 X
TAILLAMP CHROME MOULDING LH	1	\$ 175.00	11 X

\$ 25,912.58

LESS 10% \$ 2,591.26

SUB TOTAL \$ 23,321.32

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR BUMPER CLIP	1 SET	\$ 50.00	RE 30 S/N
REAR NUMBER PLATE W/GARNISH	1	\$ 90.00	RE 40 S/N
REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 50.00	11 X
1st REVERSE CAMERA	1 set	\$ 800.00	Image: 680 S/N
REVERSE SENSOR	1	\$ 480.00	CRG 200 S/N
REVERSE SENSOR HOLDER	1	\$ 80.00	11 X
COMPANY STICKER Auto	1	\$ 200.00	RE 50 S/N
JOINT SEALANT Rear windscreen	1	\$ 120.00	RE 40 S/N
SUB TOTAL		\$	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	1	\$ 150.00	30
REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR	1	\$ 200.00	120
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	30
REMOVE AND REFIT REAR ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 200.00	60
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,800.00	1000
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	1	\$ 1,800.00	1000
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	1	\$ 200.00	60

SUB TOTAL \$ 4,470.00

601AC 29,741.32

P-14584.7
10%

13126.23
1040
2300
16466.23
13122