

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLZ2653Z**
 MODEL : **OPEL CROSSLAND**
 DATE OF ACCIDENT : 27.10.2024
 TIME OF ACCIDENT : 18:40 HOURS

22	REAR FENDER LH <i>Repis</i>	1	\$ 1,903.00	\$ 1,903.00	+
23	REAR FENDER QUARTER GLASS LH <i>new</i>	1	\$ 457.00	\$ 457.00	+
24	REAR FENDER INNER TRIM LH <i>3rd</i>	1	\$ 538.00	\$ 538.00	+
25	REAR FENDER COWLING LH <i>new</i>	1	\$ 229.00	\$ 229.00	+
26	REAR END PANEL <i>Dented</i>	1	\$ 759.00	\$ 759.00	—
27	REAR END PANEL TOP GARNISH <i>Cracked</i>	1	\$ 251.00	\$ 251.00	—
28	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 824.00	\$ 824.00	+
29	REAR FLOOR PANEL <i>Repis</i>	1	\$ 1,384.00	\$ 1,384.00	+
30	REAR SPARE TYRE CHAIN BRACKET <i>3rd</i>	1	\$ 438.00	\$ 438.00	+
31	REAR SPARE TYRE CHAIN BARCKET BOLT <i>new</i>	1	\$ 112.00	\$ 112.00	+
32	REAR AXLE <i>2</i>	1	\$ 4,453.00	\$ 4,453.00	+
33	REAR WHEEL HUP C/W BEARING LH <i>HP</i>	1	\$ 427.00	\$ 427.00	+
34	REAR SHOCK ABSORBER LH <i>W</i>	1	\$ 706.00	\$ 706.00	+
35	REAR ABS SENSOR LH <i>✓</i>	1	\$ 385.00	\$ 385.00	+

8599

7739.10

TOTAL PRICE \$ 25,309.00
 LESS 10% \$ 2,530.90
 SUB TOTAL PRICE \$ 22,778.10

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	TAILGATE WINDSCREEN SEALANT <i>3rd</i>	1	\$ 80.00	\$ 80.00	40
5	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
3	REAR FENDER SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
4	REAR FENDER GLASS SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
6	REAR FENDER INNER SHIELD CLIPS (SET) <i>HP</i>	1	\$ 60.00	\$ 60.00	+
7	REAR FENDER INNER COWLING CLIP (SET) <i>W</i>	1	\$ 50.00	\$ 50.00	+
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 120.00	\$ 120.00	60
10	TRAIANGLE BREAKDOWN SIGN <i>new</i>	1	\$ 180.00	\$ 180.00	+
11	REVERSE SENSOR <i>Repaired</i>	1	\$ 220.00	\$ 220.00	+

TOTAL \$ 1,210.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

160

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLZ2653Z**
 MODEL : OPEL CROSSLAND
 DATE OF ACCIDENT : 27.10.2024
 TIME OF ACCIDENT : 18:40 HOURS

S/N	JOB DESCRIPTION	PRICE	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,200.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	TUFF COAT	\$ 250.00	60
4	WIRING BULB CHECKING	\$ 100.00	30
5	REMOVE & REFIX UPHOLSTERY TO FACILITATE REPAIR	\$ 150.00	60
6	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	+
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	+
10	REMOVE & REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	REMOVE AND REFIX REAR FENDER QUARTER GLASS LH	\$ 100.00	+
12	REMOVE AND REFIX FUEL TANK	\$ 150.00	+
13	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	+
14	FOUR WHEEL ALIGNMENT	\$ 120.00	+

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLZ2653Z**
 MODEL : OPEL CROSSLAND
 DATE OF ACCIDENT : 27.10.2024
 TIME OF ACCIDENT : 18:40 HOURS

15	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$	80.00 50
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00 X

2130

TOTAL \$ 6,190.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 23,988.10
 TOTAL LABOUR COST : \$ 6,190.00
 TOTAL REPAIR COST : \$ 30,178.10

Admin Lj
L/S 29/10/24
OTD days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

total: 10029.10
L/S: 8K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: