

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 21.10.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNR8166S**
MODEL : **VOLKSWAGEN GOLF**
DATE OF ACCIDENT : 01.10.2024
TIME OF ACCIDENT : 17:30 HOURS

Xiao Chen.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,999.60	\$ 1,999.60
2	TAILGATE DAMPER <i>non</i>	2	\$ 188.96	\$ 377.92
3	TAILGATE EMBLEM 'GOLF' <i>hu</i>	1	\$ 115.77	\$ 115.77
4	TAILGATE INNER TRIM <i>Cracked</i>	1	\$ 438.96	\$ 438.96
5	TAILGATE TOP LOCK <i>non</i>	1	\$ 388.54	\$ 388.54
6	TAILGATE LOWER LOCK <i>non</i>	1	\$ 568.75	\$ 568.75
7	TAILGATE LOGO WITH HANDLE <i>non</i>	1	\$ 996.55	\$ 996.55
8	TAILGATE WINDSCREEN MOULDING C/W GLASS <i>hu</i>	1	\$ 1,511.60	\$ 1,511.60
9	TAILGATE WEATHESTRIIP <i>ct</i>	1	\$ 635.60	\$ 635.60
10	TAILGATE LAMP <i>non</i>	2	\$ 747.65	\$ 1,495.30
11	TAIL LAMP <i>Lt Cracked</i>	2	\$ 833.51	\$ 1,667.02
12	REAR BUMPER <i>Dented</i>	1	\$ 1,588.40	\$ 1,588.40
13	REAR BUMPER DIFFUSER <i>Cracked</i>	1	\$ 498.50	\$ 498.50
14	REAR BUMPER REFLECTOR <i>non</i>	2	\$ 180.17	\$ 360.34
15	REAR BUMPER NUMBER PLATE LAMP <i>non</i>	2	\$ 99.87	\$ 199.74
16	REAR BUMPER CENTER BEAM <i>Cracked</i>	1	\$ 41.60	\$ 41.60
17	REAR BUMPER SIDE BRACKET <i>non</i>	2	\$ 198.50	\$ 397.00
18	REAR BUMPER REINFORCEMENT <i>non</i>	1	\$ 659.46	\$ 659.46
19	REAR FENDER INNER TRIM <i>non</i>	2	\$ 535.60	\$ 1,071.20
20	REAR END PANEL <i>Dented</i>	1	\$ 1,599.60	\$ 1,599.60
21	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 346.87	\$ 346.87

1710-
+
185
395
933.51
640
1295
1010

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNR8166S**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 01.10.2024
 TIME OF ACCIDENT : 17:30 HOURS

22	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 698.75	\$ 698.75	+
23	REAR TOOLS SPONGE <i>new</i>	1	\$ 189.98	\$ 189.98	+
24	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 90.97	\$ 90.97	+

7115.24
6403.71

TOTAL PRICE \$ 17,938.02
 LESS 10% \$ 1,793.80
SUB TOTAL PRICE \$ 16,144.22

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	-
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
4	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	REAR FENDER COWLING CLIP <i>new</i>	1	\$ 40.00	\$ 40.00	+
6	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
7	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
8	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	40
9	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
10	TAILGATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 150.00	\$ 150.00	+
11	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
12	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
13	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
14	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200

450

TOTAL \$ 1,220.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	200
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	700
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNR8166S**
 MODEL : **VOLKSWAGEN GOLF**
 DATE OF ACCIDENT : 01.10.2024
 TIME OF ACCIDENT : 17:30 HOURS

6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	+
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 380.00	+

1780

TOTAL \$ 5,100.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,364.22
 TOTAL LABOUR COST : \$ 5,100.00
 TOTAL REPAIR COST : \$ 22,464.22

Adrian L
 L/s 28/10/24
 06 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP:8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Total: 8633.71

L/s: 6.9K ✓